

7.1 Introduction

This chapter contains assembly drawings and circuit schematics for the 58542 VXIbus Universal Power Meter.

Parts lists for all assemblies are contained in Chapter 6.

11" x 17" (Landscape) pages follow continuing Chapter 7 of the 58542 Publication

A3
:I PROCESSOR PC BOARD
ASSY 21418
(REFER TO SCHEMATIC 21440)



P1

P2

DEVELOPEMENT BOARD INTERFACE
A2J5

A2
DIGITAL PC BOARD ASSY
21356
(REFER TO SCHEMATIC 21357)

A1
ANALOG PC BOARD ASSY
21359
(REFER TO SCHEMATIC 21360)




P6
ECL TRIGGERS

A2J6
4 3 1

BT1
BATTERY

SEE DETAIL H
SHEET 2 (Q4)













DETAIL K
NO SCALE
CAP INSTALLATION


RADIAL LEADED
CAPACITOR ONLY

PCB


CIRCUIT SIDE







CHENUCAO




5
OK

(SH 1, 3)


-15V (SH 1)

-15V (SH 1)


7
7K




RES ARE IN OHMS, 1/SH, SH,
RES ARE IN MICROFARADS,
RES ARE IN MICROHENTYS.








CLOCK1
DATA IN 1
DATA OUT 1 (SH 4)




Ω ARE IN OHMS. 1/ΩM, ΩC.
ES ARE IN MICROFARADS.
S ARE IN MICROHENRYS.
ACTORY SELECTED VALUE.








NOTES:
1. RESISTOR VALUES
2. CAPACITOR VALUES
3. INDUCTOR VALUES
4. F.S. DENOTES FAULT





COMPONENT SIDE








5
MASK AREAS INDICATED
10 PLACES

MASK VIEW
BOTTOM SIDE OF PC







ASSEMBLY 21356 REFERENCE DESIGNATORS ARE ABBREVIATED WITH A2

- NOTES (UNLESS OTHERWISE SPECIFIED):
1. RESISTOR VALUES ARE IN OHMS, 1/4W, +/- 5%.
 2. CAPACITOR VALUES ARE IN MICROFARADS.
 3. N/L = NO LOAD

Program Examples

A.1 Introduction

This appendix contains examples of the various operating programs in the 58542 VXIbus Universal Power Meter.

The examples shown in this chapter are written in HTBasic™ format. Different languages will use different commands, but the string sent or received will always be the same. In HTBasic, the OUTPUT command sends a string to the GPIB bus. The number or variable after the word OUTPUT is the GPIB address of the instrument.

A.2 Sensor Calibration Examples

Sensors must be calibrated to the meter before performing measurements. Only one sensor at a time can be calibrated to a given 58542 VXI Power Meter input. That is, each time a sensor is calibrated to the meter using the power sweep calibration, previous calibrations for that meter input are voided automatically. Thus, assuring that the measurement system is always performing under a valid sensor calibration.

A.2.1 Sensor Calibration Example 1

The following example performs power sweep calibration of the power sensor connected to input number 2 and sends back a pass/fail flag upon completion using CAL2?

```
410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
430  WAIT 1
440      PRINT Connect the sensor to the power sensor cable.
450      INPUT Then connect the sensor to the calibrator and hit ENTER.,Dmy
460      PRINT Calibrating Sensor 2...
470      OUTPUT@Pwr_mtr,CAL2?
480      ENTER@Pwr_mtr,Pass_cal
490      IF Pass_cal=0 THEN PRINT Calibration Passed
500      IF Pass_cal=1 THEN
510          PRINT Calibration FAILED, Sensor 2 on calibrator?
560  ELSE
570      IF Pass_cal<>0 THEN PRINT Strange Response to CAL2?.Clear output Queue?
580  END IF
590  !
```

A.2.2 Sensor Calibration Example 2

The power meter measurement functions are operated to tight tolerances during sensor calibration. If the sensor passes calibration, it is a good health check of the 58542 VXI Power Meter. In general, the power meter and sensors are operating properly if they pass the calibration process. For instance, the calibration process will fail if the sensor detector elements have been damaged. Also see the self test functions, which are initiated using the *TST command or the DIAG: commands (See Table 5-1).

The following program uses the CAL? query format to perform power sweep calibration of a power sensor and sends back a pass/fail flag upon completion. Completion of the calibration function is monitored via service requests using the *OPC, operation complete command.

```
330 !
340 !#####
350 !
350 ! CALIBRATE THE SENSORS
370 !
380 !#####
390 ASSIGN@Pwr_mtr to 70101
400 CLEAR@Pwr_mtr
410 WAIT 1
420 OUTPUT@Pwr_mtr;*CLS          ! Clear status registers and error queue buffer
425 WAIT 0.3
430 OUTPUT@Pwr_mtr;*ESE 1       ! Standard Event Status Enable bit 0, Operation Complete
440 OUTPUT@Pwr_mtr;*SRE 32      ! Service Request Enable Status Byte bit 5, Standard
    ! Event Status Register
450 !
460 ON INTR 7 GOSUB Spoll_intr
470 ENABLE INTR 7;2
480 !
490 ! Calibration Routine
500 !
510 INPUT Connect the sensor to the calibrator. Then press ENTER.,Dmy
520 PRINT Calibrating Sensor 1...
525 Srq_flag=0
530 OUTPUT@Pwr_mtr;CAL1?;*OPC   ! For zeroing substitute CAL1:ZERO? for CAL1?
540 !
550 !
560 ! Now wait for srq
570 !
580 !
590 !
600 WHILE Srq_flag=0
610 END WHILE
620 !
630 ! Enter Pass/Fail Flag, This comes with query format, CAL1?, rather than command format, CAL1.
640 !
650 ENTER@Pwr_mtr;Pass_cal
660 IF Pass_cal=0 THEN PRINT Calibration Passed
670 IF Pass_cal=1 THEN
680 OUTPUT@Pwr_mtr;SYST:ERR?
690 ENTER@Pwr_mtr;Err_msg$      ! Reading an error message clears it.
700 PRINT The power meter reports the following error.,ERR_msg$
710 PRINT Calibration FAILED, sensor on calibrator?
720 ELSE
730 IF Pass_cal<>0 THEN PRINT Strange Response to CAL1?. Other Event Status Register Bits Too?
740 END IF
750 !
760 STOP
770 !
780 Spoll_intr: !
790 !
800 State=SPOLL(@Pwr_mtr)
810 PRINT SPOLL INTR::State
```

```
820  Srq_flag=1
830  ENABLE INTR 7;2
840  !
850  RETURN
860  !
870  !
880  !  END OF SENSOR CAL
890  !#####
900  !
910  END
```

A.2.3 Sensor Calibration Example 3

The following program uses the CAL format to perform power sweep calibration of a power sensor. Completion of the calibration function is monitored via service requests using the *OPC, operation complete command. The Standard Event Status Register is used to report pass/fail by asserting bit 3, value 8, the Device Dependent Error bit.

```
320  !
330  ! #####
340  !
350  ! CALIBRATE THE SENSORS
360  !
370  ! #####
380  !
390  ASSIGN@Pwr_mtr to 70101
400  CLEAR@PWR_mtr
410  WAIT 1
420  OUTPUT@Pwr_mtr;*CLS          ! Clear status registers and error queue buffer
425  WAIT 0.3
430  OUTPUT@Pwr_mtr;*ESE 1       ! Standard Event Status Enable bit 0, Operation complete
440  OUTPUT@Pwr_mtr;*SRE 32      ! Service Request Enable Status Byte bit 5,
                                ! Standard Event Status Register
450  !
460  ON INTR 7 GOSUB Spoll_intr
470  ENABLE INTR 7;2
480  !
490  ! Calibration Routine
500  !
510  INPUT Connect the sensor to the calibrator. Then press ENTER.,Dmy
520  PRINT Calibrating Sensor 1
525  Srq_flag=0
530  OUTPUT@Pwr_mtr;CAL1;*OPC     ! For zeroing substitute CAL1:ZERO for CAL1
540  OUTPUT@Pwr_mtr;*OPC         ! If not sent with previous line, send *OPC here
550  !
560  ! Now wait for srq
570  !
580  !
590  !
600  WHILE Srq_flag=0
610  END WHILE
620  !
630  ! Enter Error Reporting From Standard Event Status Register
640  !
650  OUTPUT@Pwr_mtr;*ESR?
660  ENTER@Pwr_mtr;Esr
670  IF Esr=0 THEN PRINT Operation was not completed. Also, no errors.
680  IF Esr=1 THEN
690  PRINT Operation Completed. No errors reported during CAL execution.
700  ELSE
710  IF Pass_cal<>0 THEN PRINT Operation completed. An error has occurred or power
    was just turned on.
720  OUTPUT@Pwr_mtr;SYST:ERR?
730  ENTER@Pwr_mtr;Err_msg$      ! Reading an error message clears it
```

```
740 PRINT The power meter reports the following error.,Err_msg$
750 PRINT Calibration FAILED, sensor on calibrator?
760 PRINT Esr
770 !
780 END IF
790 !
800 !
810 STOP
820 !
830 Spoll_intr:~
840 !
850 State=SPOLL(@Pwr_mtr)
860 PRINT SPOLL INTR:~;State
870 Srq_flag=1
880 ENABLE INTR 7;2
890 !
900 RETURN
910 !
920 !
930 ! END OF SENSOR CAL
940 ! #####
950 !
960 END
```

A.2.4 Sensor Calibration Example 4

The following program prompts the user to connect a return loss bridge for calibration and attach an open or short to the bridge test port. It then performs a power sweep calibration and sends back a pass/fail flag upon completion.

```
410 ASSIGN @Pwr_mtr to 70101
420 CLEAR @Pwr_mtr
430 WAIT 1
440 PRINT Connect the 80503 Precision Return Loss Bridge to the input #2 power sensor cable.
445 PRINT Connect the open or short calibration connector to the bridge test port.
450 INPUT Then use an adapter to connect the bridge input port to the calibrator and hit ENTER.,Dmy
460 PRINT Calibrating Sensor 2...
470 OUTPUT @Pwr_mtr;CAL2?
480 ENTER @Pwr_mtr;Pass_cal
490 IF Pass_cal=0 THEN PRINT Calibration Passed
500 IF Pass_cal=1 THEN
510 PRINT Calibration FAILED, Bridge connected to calibrator?
560 ELSE
570 IF Pass_cal<>0 THEN PRINT Strange Response to CAL2?. Clear output Queue?
580 END IF
590 !
```

A.2.5 Sensor Calibration Example 5

The following program prompts the user to remove the high power attenuator from a high power sensor main housing and connect the main housing to the power sweep calibrator port. It then performs a power sweep calibration and sends back a pass/fail flag upon completion.

```
410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
430  WAIT 1
440  PRINT Connect the 80325 50W Power Sensor to the input #2 power sensor cable.
445  PRINT Remove the high power attenuator or leave it attached to the measurement port on the DUT
450  INPUT Then connect the high power sensor main housing to the calibrator and hit ENTER.,Dmy
460  PRINT Calibrating Sensor 2...
470  OUTPUT @Pwr_mtr;CAL2?
480  ENTER @Pwr_mtr;Pass_cal
490  IF Pass_cal=0 THEN PRINT Calibration Passed. Re-attach the high power attenuator immediately!
500  IF Pass_cal=1 THEN
510  PRINT Calibration FAILED, Main sensor housing connected to calibrator?
560  ELSE
570  IF Pass_cal<>0 THEN PRINT Strange Response to CAL2?. Clear output Queue?
580  END IF
590  !
```

A.3 Sensor Zeroing Examples

A.3.1 Sensor Zeroing Example 1

The following example requests that the operator turn off the signal source or disconnect the sensor from the source prior to zeroing. It is preferable to disable the source and leave the sensor attached to the measurement port for proper zeroing. If the source cannot be disabled, use a switch or attach a connector to the grounded metal near the DUT measurement port. DO NOT attach the sensor to the power meter's calibrator port. The zeroing offset process will account for the DUT's ground plane noise and thermal emf, not the power meter's.

```

410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
430  WAIT 1
440  INPUT Disable the source's RF output or attach it to a grounded connector. Then hit ENTER.,Dmy
450  PRINT Zeroing Sensor 1
460  OUTPUT @Pwr_mtr;CAL1:ZERO?
470  ENTER @Pwr_mtr;Pass_zer
480  IF Pass_zer=0 THEN PRINT Zeroing Passed
490  IF Pass_zer=1 THEN
500  PRINT Zeroing FAILED, Source turned off?
550  ELSE
560  IF Pass_zer<>0 THEN PRINT Strange Response to CAL1:ZERO?. Clear output Queue?
570  END IF
580  !

```

A.3.2 Sensor Zeroing Example 2

The following program turns off the signal source, zeros the power sensor, reports a pass/fail indicator upon completion, and turns the source back on.

```

400  ASSIGN @Pwr_mtr to 70101
410  ASSIGN @Source to 70102
420  CLEAR @Pwr_mtr
430  WAIT 1
440  OUTPUT @Source RF0! Turns source output power off (<-90 dBm).
450  PRINT Zeroing Sensor 1
460  OUTPUT @Pwr_mtr;CAL1:ZERO?
470  ENTER @Pwr_mtr;Pass_zer
480  IF Pass_zer=0 THEN PRINT Zeroing Passed
490  IF Pass_zer=1 THEN
500  Ques$=Zeroing FAILED, Source turned off?
510  OUTPUT @Pwr_mtr;SYST:ERR?
520  ENTER @Pwr_mtr;Err_msg$! Reading an error message clears it.
530  PRINT Err_msg$
540  PRINT Ques$
550  ELSE
560  IF Pass_zer <>0 THEN PRINT Strange Response to CAL1:ZERO?. Clear output Queue?
570  END IF
580  !
590  OUTPUT @Source RF1! Turns source output power back on.

```

Zeroing is recommended whenever performing critical final power measurements in the bottom 15 to 20 dB of a power sensors dynamic range. Zeroing removes zero drift error from the measurement. At higher power levels, zero drift is typically insignificant when compared to the other sources of error such as source/sensor mismatch uncertainty.

A.3.3 Error Control Examples

Selected basic SCPI syntax and execution errors apply to these commands.

The following command will operate properly.

```
460 OUTPUT @Pwr_mtr;CAL1?          ! Calibrate channel 1
```

The following command is not a legal command. The 58542 only has two channels.

```
460 OUTPUT @Pwr_mtr;CAL3?          ! Calibrate channel 3
```

If the user asks for error information, the error reporting is as follows:

```
510 OUTPUT @Pwr_mtr;SYST:ERR?
520 ENTER @Pwr_mtr;Err_msg$        ! Reading an error message clears it.
530 PRINT Err_msg$
Program Output:
-7,Invalid Error Number
```

The following command is not a legal command. The command is mis-typed.

```
460 OUTPUT @Pwr_mtr;CALS?          ! Calibrate channel 3
```

If the user asks for error information, the error reporting is as follows.

```
510 OUTPUT @Pwr_mtr;SYST:ERR?
520 ENTER @Pwr_mtr;Err_msg$        ! Reading an error message clears it.
530 PRINT Err_msg$
Program Output:
-113,Undefined Header;CALS
Device-specific errors include the following.
-300,Device-specific error;No Sensor
```

The following examples demonstrate the conditions for various errors.

```
380 ASSIGN @Pwr_mtr to 70101
390 CLEAR @Pwr_mtr
400 WAIT 1
401 INPUT Disconnect Sensor From Cable for Error Demonstration. Then hit ENTER.,Dmy
410 PRINT Calibrating Sensor 1
420 OUTPUT @Pwr_mtr;CAL1?
430 ENTER @Pwr_mtr;Pass_cal
440 IF Pass_cal=0 THEN PRINT Calibration Passed
450 IF Pass_cal=1 THEN
460 Ques$=Calibration FAILED, sensor on calibrator?
470 OUTPUT @Pwr_mtr;SYST:ERR?
480 ENTER @Pwr_mtr;Err_msg$        ! Reading an error message clears it.
490 PRINT Err_msg$
500 PRINT Ques$
520 ELSE
521 IF Pass_cal<>0 THEN PRINT Strange Response to CAL1?. Clear output Queue?
530 END IF
531 !
532 !
533 STOP
Program Output:
Calibrating Sensor 1
```

-300, Device-specific error;No Sensor
Calibration FAILED, sensor on calibrator?

```
410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
440  WAIT 1
450  INPUT Disconnect the sensor from the cable 1 second after hitting ENTER. Hit ENTER.,Dmy
460  PRINT Calibrating Sensor 1
470  OUTPUT @Pwr_mtr;CAL1?
480  ENTER @Pwr_mtr;Pass_cal
490  IF Pass_cal=0 THEN PRINT Calibration Passed
500  IF Pass_cal=1 THEN
510    Ques$=Calibration FAILED, sensor on calibrator?
520    OUTPUT @Pwr_mtr;SYST:ERR?
530    ENTER @Pwr_mtr;Err_msg$      ! Reading an error message clears it.
540    PRINT Err_msg$
550    PRINT Ques$
560  ELSE
570    IF Pass_cal<>0 THEN PRINT Strange Response to CAL1?. Clear output Queue?
580  END IF
590  !
600  !
610  STOP
```

Program Output:

Calibrating Sensor 1
-300, Device-specific error;Sensor not connected to calibrator
Calibration FAILED, sensor on calibrator?

```
410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
440  WAIT 1
450  INPUT Do not connect the sensor to the calibrator. Hit ENTER.,Dmy
460  PRINT Calibrating Sensor 1
470  OUTPUT @Pwr_mtr;CAL1?
480  ENTER @Pwr_mtr;Pass_cal
490  IF Pass_cal=0 THEN PRINT Calibration Passed
500  IF Pass_cal=1 THEN
510    Ques$=Calibration FAILED, sensor on calibrator?
520    OUTPUT @Pwr_mtr;SYST:ERR?
530    ENTER @Pwr_mtr;Err_msg$      ! Reading an error message clears it.
540    PRINT Err_msg$
550    PRINT Ques$
560  ELSE
570    IF Pass_cal<>0 THEN PRINT Strange Response to CAL1?. Clear output Queue?
580  END IF
590  !
600  !
610  STOP
```

Program Output:

Calibrating Sensor 1
-300, Device-specific error;Sensor not connected to calibrator
Calibration FAILED, sensor on calibrator?

```
410  ASSIGN @Pwr_mtr to 70101
420  CLEAR @Pwr_mtr
440  WAIT 1
449  PRINT Connect the sensor to the calibrator.
450  INPUT Remove the sensor 10 seconds after hitting ENTER. Hit ENTER.,Dmy
460  PRINT Calibrating Sensor 1

470  OUTPUT @Pwr_mtr;CAL1?
480  ENTER @Pwr_mtr;Pass_cal
490  IF Pass_cal=0 THEN PRINT Calibration Passed
```

```
500 IF Pass_cal=1 THEN
510     Ques$=Calibration FAILED, sensor on calibrator?
520     OUTPUT @Pwr_mtr;SYST:ERR?
530     ENTER @Pwr_mtr;Err_msg$    ! Reading an error message clears it.
540     PRINT Err_msg$
550     PRINT Ques$
560 ELSE
570     IF Pass_cal<>0 THEN PRINT Strange Response to CAL1?. Clear output Queue?
580     END IF
590     !
600
610     STOP
```

Program Output:

```
Calibrating Sensor 1
-300,Device-specific error;Sensor calibration error
Calibration FAILED, sensor on calibrator?
```

```
410 ASSIGN @Pwr_mtr to 70101
420 CLEAR @Pwr_mtr
430 WAIT 1
440 INPUT Connect the sensor to a source set to about 0dBm. Hit ENTER.,Dmy
450 PRINT Zeroing Sensor 1
460 OUTPUT @Pwr_mtr;CAL1:ZERO?
470 ENTER @Pwr_mtr;Pass_zer
480 IF Pass_zer=0 THEN PRINT Zeroing Passed
490 IF Pass_zer=1 THEN
500     Ques$=Zeroing FAILED, Source turned off?
510     OUTPUT @Pwr_mtr;SYST:ERR?
520     ENTER @Pwr_mtr;Err_msg$! Reading an error message clears it.
530     PRINT Err_msg$
540     PRINT Ques$
550 ELSE
560     IF Pass_zer<>0 THEN PRINT Strange Response to CAL1:ZERO?. Clear output Queue?
570 END IF
580 !
590 !
600 STOP
```

Program Output:

```
Zeroing Sensor 1
-300,Device-specific error;Sensor zeroing error
Zeroing FAILED, Source turned off?
```

```
410 ASSIGN @Pwr_mtr to 70101
420 CLEAR @Pwr_mtr
430 WAIT 1
440 INPUT Disconnect the sensor from the sensor cable. Hit ENTER.,Dmy
450 PRINT Zeroing Sensor 1
460     OUTPUT @Pwr_mtr;CAL1:ZERO?
470     ENTER @Pwr_mtr;Pass_zer
480     IF Pass_zer=0 THEN PRINT Zeroing Passed
490     IF Pass_zer=1 THEN
500         Ques$=Zeroing FAILED, Source turned off?
510         OUTPUT @Pwr_mtr;SYST:ERR?
520         ENTER @Pwr_mtr;Err_msg$! Reading an error message clears it.
530         PRINT Err_msg$
540         PRINT Ques$
550     ELSE
560         IF Pass_zer<>0 THEN PRINT Strange Response to CAL1:ZERO?. Clear output Queue?
570     END IF
580     !
590     !
600 STOP
```

Program Output:

Zeroing Sensor 1
-300,Device-specific error;No Sensor
Zeroing FAILED, Source turned off?

A.4 Reading Power Measurement Examples

This section gives a quick start in performing measurements. Therefore, the easiest measurement commands are in the first example, MEAS#? in NORMal Mode. This may not be the optimum 58542 configuration for the user's application. There are three example groups, NORMal Mode, SWIFt Mode, and BURSt Mode. The use of the three 58542 measurement data commands, MEAS#?, READ#?, and FETCh#? are explained in detail under the NORMal Mode, which is the meter's power-on default mode.

SWIFt and BURSt Mode measurements use only FETCh#?, not READ#? or MEAS#?. In this getting started section, high speed SWIFt and BURSt Mode examples are few in number and brief in description; detailed information on high speed power measurements can be found in Section A.8 (High Speed Measurements).

A.4.1 Reading Power Measurements Example 1

The following program configures the power meter for single channel operation, and uses the MEAS#? command to perform limited Auto-Configuration and return power measurement data in NORMal Mode. Prior to executing the measurement cycle, the MEAS#? command performs low level configuration functions for averaging and trigger sequence arming automatically. Use MEAS#? to get started performing power measurements quickly. Typically, MEAS#? will satisfy most power measurement needs; however, more advanced power meter users of NORMal Mode may prefer lower level controls of the READ#? command and the higher measurement rates of the FETCh#? command. High speed measurements are performed using the SWIFt and BURSt Modes, not NORMal Mode.

Note that the MEAS#? command's measurement response speed is slower at very low power levels and faster at high power levels. This is due to a chopper stabilization system used in the NORMal Mode (also used in SWIFt Mode, but not BURSt mode) and Auto-Averaging when using SENS#:AVER:TCON REP. At the most sensitive gain ranges, chopper stabilization allows the very small voltages from the power sensor to be accurately measured. Also, at lower power meter gain ranges, Auto-Averaging automatically adds additional averaging to counter the effects of noise in the measurement signal. The extra time required to perform these Auto-Averaged measurements will not be apparent unless switching the default averaging control, SENS#:AVER:TCON MOV, to SENS#:AVER:TCON REP.

When using the MEAS#? command, Auto-Averaging is automatically set to ON. If another part of programming was using manual averaging, be sure to turn Auto-Averaging back off (SENS#:AVER:COUN:AUTO OFF) before exiting the section of the program code using MEAS#. When operating in NORMal Mode the user can always use the SENS#:AVER:COUN? query to find out the current averaging value for a particular sensor, and the SENS#:AVER:COUN ### command to set a higher or lower averaging value.

```
260  ASSIGN @Pwr_mtr to 70101
270  CLEAR @Pwr_mtr
280    WAIT 1
290  OUTPUT @Pwr_mtr;CALC1:MODE NORM! Can ONLY send Configuration Commands in Normal Mode!!
300  OUTPUT @Pwr_mtr;CALC1:POW 1      ! Channel 1 configured to measure sensor 1 power
310  !
320  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                   ! Applies Cal Factor for 1.44 GHz to measurement data.
330  !
340  FOR I=1 TO 10
350    OUTPUT @Pwr_mtr;MEAS1?      ! Measures Power at sensor.
360    ENTER @Pwr_mtr;Rdg
370    PRINT Rdg
380  NEXT I
390  !
510  END
```

A.4.2 Reading Power Measurements Example 2

If sending the MEAS#? command, two configuration changes occur. These are listed as shown below. To perform measurements without changing the configuration, use the READ#? command.

Command/Configuration Item	MEAS#? Auto-Setting
SENS#:A VER:COUN:AUTO	ON
INIT:CONT	OFF

No other items than the above will change configuration when sending the MEAS#? command.

The following example illustrates that Auto-Averaging changes the active averaging number. Since Auto-Averaging was activated through use of the MEAS#? command, the averaging value currently in use when Auto-Averaging is set to OFF is taken as the new averaging number. This is likely to differ from the averaging number in effect before the MEAS#? command was sent. If this is an undesirable effect, remember to read the averaging number using SENS#:AVER:COUN? and store the value for post Auto-Averaging output at the conclusion of the MEAS#? power meter reading measurement routine.

```

260  ASSIGN @Pwr_mtr to 70101
270  CLEAR @Pwr_mtr
290  WAIT 1
300  OUTPUT @Pwr_mtr;CALC1:MODE NORM
310  OUTPUT @Pwr_mtr;SENS1:AVER:COUN:AUTO OFF
320  OUTPUT @Pwr_mtr;SENS1:AVER:COUN:AUTO?
330  ENTER @Pwr_mtr;A$
340  PRINT A$,1 is AUTO ON
350  OUTPUT @Pwr_mtr;SENS1:AVER:COUN 16
360  OUTPUT @Pwr_mtr;SENS1:AVER:COUN?
370  ENTER @Pwr_mtr;A$
380  PRINT A$,16 MEANS AVERAGING #=16 ACCEPTED.
390  OUTPUT @Pwr_mtr;INIT:CONT ON
400  OUTPUT @Pwr_mtr;INIT:CONT?
410  ENTER @Pwr_mtr;A$
420  PRINT A$,1 is INIT:CONT ON
430  OUTPUT @Pwr_mtr;CALC1:POW 1           ! Channel 1 configured to measure sensor 1 power
440  !
450  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
      ! Applies Cal Factor for 1.44 GHz.
460  !
470  FOR I=1 TO 10
480      OUTPUT @Pwr_mtr;MEAS1?           ! Measures Power at sensor.
490      ENTER @Pwr_mtr;Rdg
500      PRINT Rdg
510  NEXT I
520  !
530  OUTPUT @Pwr_mtr;SENS1:AVER:COUN:AUTO?
540  ENTER @Pwr_mtr;A$
550  PRINT A$,1 is AUTO ON
560  OUTPUT @Pwr_mtr;INIT:CONT?
570  ENTER @Pwr_mtr;A$
580  PRINT A$,1 is INIT:CONT ON
590  OUTPUT @Pwr_mtr;SENS1:AVER:COUN:AUTO OFF
600  OUTPUT @Pwr_mtr;SENS1:AVER:COUN:AUTO?
610  ENTER @Pwr_mtr;A$
620  PRINT A$,1 is AUTO ON
630      OUTPUT @Pwr_mtr;SENS1:AVER:COUN?
640      ENTER @Pwr_mtr;A$
650      PRINT A$,Value not equal to 16 means reset by Auto-Averaging during MEAS#?
760  !
770  END

```

A.4.3 Reading Power Measurements Example 3

The following program configures the power meter for dual channel operation and uses the MEAS#? command to return power measurement data in NORMal Mode. Please note that measurement speed per channel decreases slightly in NORMal mode when two channels, versus only a single channel, are connected and calibrated. In NORMal Mode, single channel measurement rates are slightly faster than two channel measurement rates. If using CW power sensors, also please note that power measurements are not performed at specifically the exact, simultaneous instant in time. In NORMal Mode there will be a short time delay of about 3 ms between the two channels' sample points, about two and a half orders of magnitude faster than traditional CW power meters. In BURSt and SWIFT mode this time is about 1 ms. If the user needs to guarantee that power sampling occurs on both channels within a smaller interval of time, this can be accomplished to within about 2% of the Sample Delay time plus 2 ns using the Series 80350A Peak Power Sensors and triggering both sensors at the same time. The example below operates with either Peak or CW power sensors.

```
260  ASSIGN @Pwr_mtr to 70101
270  CLEAR @Pwr_mtr
280  WAIT 1
290  OUTPUT @Pwr_mtr;CALC1:MODE NORM ! Can ONLY send Configuration Commands in Normal Mode!!
300  OUTPUT @Pwr_mtr;CALC1:POW 1      ! Channel 1 configured to measure sensor 1 power
310  OUTPUT @Pwr_mtr;CALC1:UNIT W    ! Transmitter output power in Watts.
320  OUTPUT @Pwr_mtr;CALC2:RAT 1,2   ! Transmitter gain stays in default, dBm.
330  !
340  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
      ! Applies Cal Factor for 1.44 GHz to sensor 1 data.
350  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 0.96E9
      ! Applies Cal Factor for 960 MHz to sensor 2 data.
360  !
370  FOR I=1 TO 10
380      OUTPUT @Pwr_mtr;MEAS1?;MEAS2? ! Measures Power at sensors.
390      ENTER @Pwr_mtr;Chn_pow 1
400      ENTER @Pwr_mtr;Chn_1rat2
410      PRINT Chn_pow1,Chn_1rat2
420  NEXT I
430  !
550  END
```

A.4.4 Reading Power Measurements Example 4

The following program configures the power meter for single channel operation and uses the READ#? command to return power measurement data in NORMal Mode. Using the READ#? command will not change power meter configuration items under any circumstances. Note that INIT:CONT ON is illegal when using READ#?. When continuous trigger arming is desired, use INIT:CONT ON with the FETCh#? command if desired. Also, use TRIG:SOUR IMM when using the READ#? command.

```

280  ASSIGN @Pwr_mtr to 70101
290  CLEAR @Pwr_mtr
300  WAIT 1
310  OUTPUT @Pwr_mtr;CALC1:MODE NORM! Can ONLY send Configuration Commands in Normal Mode!!
320  OUTPUT @Pwr_mtr;TRIG:SOUR IMM      ! TRIG:SOUR must be IMM when using READ#?
330  OUTPUT @Pwr_mtr;INIT:CONT OFF      ! INIT:CONT arming must be OFF when using READ#?
340  !
350  OUTPUT @Pwr_mtr;SENS2:AVER:COUN 1! Sets averaging to manual and one sample per reading.
360  OUTPUT @Pwr_mtr;CALC1:POW 2        ! Channel 1 configured to measure sensor 2 power
370  !
380  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 17.4E9
                                     ! Applies Cal Factor for 17.4 GHz to measurement data.
390  !
400  FOR I=1 TO 10
410  OUTPUT @Pwr_mtr;READ2?            ! Measures Power at sensor.
420      ENTER @Pwr_mtr;Rdg
430      PRINT Rdg
440  NEXT I
450  !
650  END

```

A.4.5 Reading Power Measurements Example 5

READ#? measurement response speed is slower at very low power levels and faster at high power levels. This is due to a chopper stabilization system used in the NORMal Mode which is also used in the SWIFT Mode, but not the BURSt mode. At the most sensitive gain ranges, chopper stabilization allows the very small voltages from the power sensor to be accurately measured.

The following program configures the power meter for dual channel operation and uses the READ#? command to return power measurement data in NORMal Mode.

```
260  ASSIGN @Pwr_mtr to 70101
270  CLEAR @Pwr_mtr
280  WAIT 1
290  OUTPUT @Pwr_mtr;CALC1:MODE NORM! Can ONLY send Configuration Commands in Normal Mode!!
300  OUTPUT @Pwr_mtr;CALC1:POW 1           ! Channel 1 configured to measure sensor 1 power
310  OUTPUT @Pwr_mtr;CALC1:UNIT W         ! Transmitter output power in Watts.
320  OUTPUT @Pwr_mtr;CALC2:RAT 1,2       ! Transmitter gain stays in default, dBm.
330  !
340  OUTPUT @Pwr_mtr;TRIG:SOUR IMM        ! TRIG:SOUR must be IMM when using READ#?
350  OUTPUT @Pwr_mtr;INIT:CONT OFF      ! INIT:CONT arming must be OFF when using READ#?
360  !
370  OUTPUT @Pwr_mtr;SENS1:AVER:COUN 1
                                     ! Sets averaging to manual and one sample per reading.
380  OUTPUT @Pwr_mtr;SENS2:AVER:COUN 16
                                     ! Sets averaging to manual and 16 samples per reading.
390  !
400  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                     ! Applies Cal Factor for 1.44 GHz to sensor 1 data.
410  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 0.96E9
                                     ! Applies Cal Factor for 960 MHz to sensor 2 data.
420  !
430  FOR I= 1 TO 10
440      OUTPUT @Pwr_mtr;READ1?;READ2?  ! Measures Power at sensors.
450      ENTER @Pwr_mtr;Chn_pow1
460      ENTER @Pwr_mtr;Chn_1rat2
470      PRINT Chn_pow1,Chn_1rat2
480  NEXT I
490  !
610  END
```

A.4.6 Reading Power Measurements Example 6

FETCh#? allows finer control of the meter's measurement sequences. The low level control function of FETCh#? is to first, process the measurement channel information based upon sensor data and configuration settings and then, place the result in the meter data output buffer to be read by the slot 0 controller/resource manager.

The following program uses the INIT command to control acceptance of measurement values in conjunction with the FETCh#? command. When using FETCh#?, both trigger sequence arming and triggering/data acquisition must be controlled in the program. This is juxtaposed with MEAS#? and READ#? which, being higher level commands, include these functions.

This program will allow the fastest measurement speed performance in NORMal mode.

```

280  ASSIGN @Pwr_mtr to 70101
290  CLEAR @Pwr_mtr
300  WAIT 1
310  OUTPUT @Pwr_mtr;CALC1:MODE NORM! Can ONLY send Configuration Commands in Normal Mode!!
320  OUTPUT @Pwr_mtr;TRIG:SOUR IMM          ! Power Meter controls triggering with TRIG or *TRG
330  OUTPUT @Pwr_mtr;INIT:CONT ON          ! Power Meter controls instrument trigger arming
340  !
350  OUTPUT @Pwr_mtr;SENS2:AVER:COUN 1      ! Sets averaging to manual and one sample per reading.
360  OUTPUT @Pwr_mtr;CALC1:POW 2          ! Channel 1 configured to measure sensor 2 power
370  !
380  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 17.4E9
                                           ! Applies Cal Factor for 17.4 GHz to data.
390  !
400  FOR I=1 TO 10
430      OUTPUT @Pwr_mtr;FETC1?            ! Measures Power at sensor.
440      ENTER @Pwr_mtr;Rdg
450      PRINT Rdg
460  NEXT I
470  !
670  END

```

A.4.7 Reading Power Measurements Example 7

The following example is similar to the example above; however, it now uses TRIG:SOUR BUS instead of IMMEDIATE so that triggering is controlled by the TRIG command. EXT or TTLT triggering can not be used in NORMal Mode. Additionally, INIT:CONT is set to OFF, allowing the INIT (or INIT:IMM) command to control arming of the triggering cycle.

```
280  ASSIGN Pwr_mtr to 70101
290  CLEAR @Pwr_mtr
300  WAIT 1
310  OUTPUT @Pwr_mtr;CALC1:MODE NORM! Can ONLY send Configuration Commands in Normal Mode!!
320  OUTPUT @Pwr_mtr;TRIG:SOUR BUS           ! Program controls triggering with TRIG or *TRG
330  OUTPUT @Pwr_mtr;INIT:CONT OFF          ! Program controls instrument trigger arming
340  !
350  OUTPUT @Pwr_mtr;SENS2:AVER:COUN 1      ! Sets averaging to manual and one sample per reading.
360  OUTPUT @Pwr_mtr;CALC1:POW 2           ! Channel 1 configured to measure sensor 2 power
370  !
380  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 17.4E9 ! Applies Cal Factor for 17.4 GHz to data.
390  !
400  FOR I=1 TO 10
410      OUTPUT @Pwr_mtr;INIT                ! INIT arms the triggering and measurement cycle
420      OUTPUT @Pwr_mtr;TRIG                ! BUS trigger
430      OUTPUT @Pwr_mtr;FETC1?              ! Measures Power at sensor.
440      ENTER @Pwr_mtr;Rdg
450      PRINT Rdg
460  NEXT I
470  !
670  END
```

A.4.8 Reading Power Measurements Example 8

The following program shows fast BUS triggering in the SWIFt Mode. TRIG (or *TRG) is used to acquire data, and FETCh#? processes and outputs the data to the slot 0 controller/resource manager. This program does not use the meter's data buffering capability.

```

170 ASSIGN @Pwr_mtr to 70101
180 CLEAR @Pwr_mtr
190 WAIT 1
200 OUTPUT @Pwr_mtr;*CLS           ! Clears old messages from SYST:ERR buffer
205 WAIT 0.3
210 PRINT Running...
220 !
230 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode to perform channel configuration
240 OUTPUT @Pwr_mtr;CALC1:POW 1     ! Channels 1 or 2 can be either POW 1 or POW 2
250                                ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
260 !
270 !#####
280 !
290 ! Entering SWIFt Mode
300 !
310 OUTPUT @Pwr_mtr;CALC1:MODE SWIF ! Enters SWIFt Mode for fastest individual data point
                                     ! triggered measurements.
320 !
330 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                     ! Applies Cal Factor in SWIFt mode
340                                ! Can be sent before or after CALC#:MODE SWIF
350 !
360 OUTPUT @Pwr_mtr;TRIG:SOUR BUS   ! BUS or EXT triggering is slower than IMM
370                                ! Can be sent before or after CALC#:MODE SWIF
380 !
390 FOR I=1 TO 10
400     FOR K=1 TO 20
410         OUTPUT @Pwr_mtr;TRIG     ! TRIG is the SCPI Bus trigger. Can also use *TRG
420         OUTPUT @Pwr_mtr;FETC1?   ! FETC#? acquires data
430         ENTER @Pwr_mtr;Chan1sens_1(K)
440         !ENTER @Pwr_mtr;Chan1sens_1(K),Chan2sens_2(K)
                                     ! Use this line when two sensors are attached.
450     NEXT K
460 !
470     PRINT Chan1sens_1(*)
480 !PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
490     PRINT ""
500 NEXT I
510 !
520 END

```

A.4.9 Reading Power Measurements Example 9

The following program uses BURSt Mode for the fastest measurement rates possible. The maximum measurement speed is performed when TRIG:DEL is set to 0. TRIG:DEL controls the speed of sampling and data buffering. When TRIG:DEL is set to 0.004, samples will be taken every 4 milliseconds, on both channels if connected, and stored in internal data buffer. This speed does not control or account for the meter's internal data processing time after data acquisition or the speed of data transfer to the controller. This second component of time, the time to get data from the 58542, is proportional to the number of data points measured. Therefore, the example below uses only one channel and keeps the number of points buffered to a minimum.

Both channels' data will be taken at the same time during BURSt Mode. Power meter measurement speed does not change when two sensors are connected versus only one sensor. However, the meter's processing time and the time to transmit the data over the VXI and GPIB interfaces takes longer due to the additional sensor data. If two sensors are connected, calibrated, and their respective channels are set to ON, then must read both arrays of data. Only read one array of data when one sensor is attached, calibrated, and set to ON.

As shown in the examples, send the CALC#:MODE BURS command prior to sending the BURSt Mode configuration commands TRIG:SOUR, TRIG:MODE, TRIG:COUN, and TRIG:DEL.

```
10  ALPHA ON
20  CLEAR SCREEN
30  !
40  OPTION BASE 1
50  DIM Id$(50),Err_msg$(70)
60  DIM Ques$(200),A$(80),Chan1sens_1(500)
70  DIM Chan2sens_2(500)
80  !
90  !
100 !#####
110 !   Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot0 TO 70100      ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101    ! 70101 is Power Meter in 1st position right of slot 0
150 !#####
160 !
170 ! Identify Attached Instruments
180 !
190 OUTPUT @Slot0;*Slot0;*IDN?
200 ENTER @Slot0;Id$
210 PRINT SLOT 0 is ;Id$
220 !
230 OUTPUT @Pwr_mtr;*IDN?
240 ENTER @Pwr_mtr;Id$
250 PRINT SLOT 1 is ;Id$
260 WAIT 1
270 !
280 !
290 CLEAR @Pwr_mtr
300 WAIT 1
310 OUTPUT @Pwr_mtr;*CLS      ! Clears old messages from SYST:ERR buffer
320 WAIT 0.3
330 OUTPUT @Pwr_mtr;CALC1:MODE NORM! NORMAl Mode to perform channel configuration
340 OUTPUT @Pwr_mtr;CALC1:POW 1 ! Channels 1 or 2 can be either POW 1 or POW 2
350 ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
360 OUTPUT @Pwr_mtr;TRIG:SOUR IMM      ! IMM set here to highlight conflict with BURSt operation.
370 !
380 !#####
390 !
400 ! Entering BURSt Mode
410 !
```

```
420 OUTPUT @Pwr_mtr;CALC1:MODE BURS      ! Enters BURSt Mode for fastest measurement speeds.
430 !
440 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.44E9
    ! Applies Cal Factor in BURSt mode
450      ! Can be sent before or after CALC#:MODE BURS
460 !
470 OUTPUT @Pwr_mtr;TRIG:SOUR BUS! IMM triggering is illegal in BURSt Mode, Use BUS or EXT.
480      ! Can be sent before or after CALC#:MODE BURS
490 !
500 OUTPUT @Pwr_mtr;TRIG:MODE POST      ! Data acquired after trigger, not before as with PRE.
510      ! Send only after CALC#:MODE BURS
520 !
530 OUTPUT @Pwr_mtr;TRIG:COUN 500      ! 500 readings acquired and stored with each trigger.
540      ! Send only after CALC#:MODE BURS, following TRIG:MODE.
550      ! Be sure COUN# matches ENTER variable dimension.
560 !REDIM Chan1sens_1(500),Chan2sens_2(500) ! REDIM to smaller array size only if necessary.
570 !
580      OUTPUT @Pwr_mtr;TRIG:DEL .000      ! 0 millisecond between rdgs setting is 5100 rdgs/sec.
590      ! Send only after CALC#:MODE BURS, following TRIG:COUN.
600 !
610 !
620 FOR I=1 TO 10
630     Time1=TIMEDATE
640     !
650     OUTPUT @Pwr_mtr;TRIG      ! TRIG is the SCPI Bus trigger. Can also use *TRG
660     OUTPUT @Pwr_mtr;FETC1?! FETC#? acquires data
670     ENTER @Pwr_mtr;Chan1sens_1(*)
680     !ENTER @Pwr_mtr;Chan1sens_1(*),Chan2sens_2(*)
    ! Use this line when two sensors are attached.
690     !
700     Time2=TIMEDATE
710     Time=Time2-Time1
720     Speed=500/Time
730     PRINT Chan1sens_1(*)
740     !PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
750     PRINT Speed; readings per second, round trip.
760     PRINT ""
770 NEXT I
780 !
790 END
```

A.5 Instrument Triggering Examples

A.5.1 TRIGgering Example 1

The following two programs illustrate the operation of TRIG:SOUR HOLD with the MEAS#? and FETCh#? measurement data queries. This first program shows TRIG:SOUR HOLD used with MEAS#?. Since MEAS#? is a high level command containing it's own trigger sequence arming, triggering, and measurement data acquisition functions, the program returns valid measurement data. The output from the SYST:ERR query is -0, No error.

```
260 ASSIGN @Pwr_mtr to 70101
270 CLEAR @Pwr_mtr
275 WAIT 1
280 OUTPUT @Pwr_mtr;*CLS           ! Clears old messages from SYST:ERR buffer
290 WAIT 0.3
300 OUTPUT @Pwr_mtr;CALC1:MODE NORM! NORMAL Mode.
310 OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channel 1 configured to measure sensor 1 power
320 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                   ! Applies Cal Factor for 1.44 GHz to data.

330 !
340 OUTPUT @Pwr_mtr;TRIG:SOUR HOLD ! Halts triggering when used with FETCh#?
350 !
360 FOR I=1 TO 10
370     OUTPUT @Pwr_mtr;MEAS1?     ! MEAS#? returns valid data with TRIG:SOUR set to HOLD.
380     ENTER @Pwr_mtr;Rdg
390     PRINT Rdg
400 NEXT I
410 !
420 OUTPUT @Pwr_mtr;SYST:ERR?     ! Query error buffer
430 ENTER @Pwr_mtr;A$
440 PRINT A$
530 END
```

A.5.2 TRIGgering Example 2

When FETCh#? is used while TRIG:SOUR is HOLD, invalid data, 9.e+40, is returned and the SYST:ERR? query returns -230, Data corrupt or stale.

```
260 ASSIGN @Pwr_mtr to 70101
270 CLEAR @Pwr_mtr
275 WAIT 1
280 OUTPUT @Pwr_mtr;*CLS           ! Clears old messages from SYST:ERR buffer
290 WAIT 0.3
300 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAL Mode.
310 OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channel 1 configured to measure sensor 1 power
320 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                   ! Applies Cal Factor for 1.44 GHz to data.

330 !
340 OUTPUT @Pwr_mtr;TRIG:SOUR HOLD ! Halts triggering when used with FETCh#?
350 !
360 FOR I=1 TO 10
370     OUTPUT @Pwr_mtr;FETC1?     ! FETC#? will not acquire valid data when TRIG:SOUR
                                   ! is set to HOLD.

380     ENTER @Pwr_mtr;Rdg
390     PRINT Rdg
400 NEXT I
410 !
420 OUTPUT @Pwr_mtr;SYST:ERR?     ! Query error buffer
430 ENTER @Pwr_mtr;A$
440 PRINT A$
530 END
```

A.5.3 TRIGgering Example 3

Please note, the READ#? measurement data query requires TRIG:SOUR IMM for proper operation. While TRIG:SOUR is HOLD, data output is also invalid, 9.e+40, but the SYST:ERR? query response is different, -214, Trigger deadlock.

```

260  ASSIGN @Pwr_mtr to 70101
270  CLEAR @Pwr_mtr
275  WAIT 1
280  OUTPUT @Pwr_mtr;*CLS           ! Clears old messages from SYST:ERR buffer
290  WAIT 0.3
300  OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode.
310  OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channel 1 configured to measure sensor 1 power
320  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                     ! Applies Cal Factor for 1.44 GHz to data.
330  !
340  OUTPUT @Pwr_mtr;TRIG:SOUR HOLD ! Halts triggering when used with FETCh#?
350  !
360  FOR I=1 TO 10
370      OUTPUT @Pwr_mtr;READ1?     ! READ#? requires TRIG:SOUR IMM not, HOLD.
380      ENTER @Pwr_mtr;Rdg
390      PRINT Rdg
400  NEXT I
410  !
420  OUTPUT @Pwr_mtr;SYST:ERR?      ! Query error buffer
430  ENTER @Pwr_mtr;A$
440  PRINT A$
530  END

```

A.5.4 TRIGgering Example 4

The following examples show the use of BUS triggering with FETCh#? in NORMAl and BURSt Modes.

```

270  ASSIGN @Pwr_mtr to 70101
280  CLEAR @Pwr_mtr
290  WAIT 1
300  OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode.
310  OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channel 1 configured to measure sensor 1 power
320  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                     ! Applies Cal Factor for 1.44 GHz to data.
330  !
340  OUTPUT @Pwr_mtr;TRIG:SOUR BUS
350  !
360  FOR I=1 TO 10
362  OUTPUT @Pwr_mtr;TRIG           ! TRIG is the SCPI Bus trigger. Can also use *TRG
370      OUTPUT @Pwr_mtr;FETC1?     ! FETC#? acquires data
380      ENTER @Pwr_mtr;Rdg
390      PRINT Rdg
400  NEXT I
410  !
530  END

```

A.5.5 TRIGgering Example 5

BURSt Mode BUS triggering with FETCh?

```
10  ALPHA ON
20  CLEAR SCREEN
30  !
40  OPTION BASE 1
50  DIM Id$(50),Err_msg$(70)
60  DIM Ques$(200),A$(80),Chan1sens_1(50)
70  DIM Chan2sens_2(50)
80  !
90  !
100 !#####
110 ! Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot0 TO 70100          ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101       ! 70101 is Power Meter, in 1st position right of slot 0
150 !#####
160 !
170 ! Identify Attached Instruments
180 !
190 OUTPUT @Slot0;*IDN?
200 ENTER @Slot0;Id$
210 PRINT SLOT 0 is ;Id$
220 !
230 OUTPUT @Pwr_mtr;*IDN?
240 ENTER @Pwr_mtr;Id$
250 PRINT SLOT 1 is ;Id$
260 WAIT 1
270 !
280 !
290 CLEAR @Pwr_mtr
300 WAIT 1
310 OUTPUT @Pwr_mtr; *CLS          ! Clears old messages from SYST:ERR buffer
320 !
330 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode to perform channel configuration
340 OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channels 1 or 2 can be either POW 1 or POW 2
350                                ! RAT and DIFF are illegal in SWIFT and BURSt Modes
360 OUTPUT @Pwr_mtr;TRIG:SOUR IMM  ! IMM set here to highlight conflict with BURSt operation
370 !
380 !#####
390 !
400 !   Entering BURSt Mode
410 !
420 OUTPUT @Pwr_mtr;CALC1:MODE BURS ! Enters BURSt Mode for fastest measurement speeds
430 !
440 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.44E9
                                     ! Applies Cal Factor in burst mode
                                     ! Can be sent before or after CALC#:MODE BURS
450
460 !
470 OUTPUT @Pwr_mtr;TRIG:SOUR BUS   ! IMM triggering is illegal in BURSt Mode, Use BUS or EXT.
480                                ! Can be sent before or after CALC#:MODE BURS
490 !
500 OUTPUT @Pwr_mtr;TRIG:MODE POST ! Data acquired after trigger, not before as with PRE.
510                                ! Send only after CALC#:MODE BURS
520 !
530 OUTPUT @Pwr_mtr;TRIG:COUN 50    ! 50 readings acquired and stored with each trigger
540                                ! Send only after CALC#:MODE BURS
550                                ! Be sure COUN# matches ENTER variable dimension.
560 !REDIM Chan1sens_1(50),Chan2sens_2(50) ! REDIM to smaller array size only if necessary
570 !
580 OUTPUT @Pwr_mtr;TRIG:DEL .001   ! 1 millisecond between rdgs, 0 ms is 5100 rdgs/sec
590                                ! Send only after CALC#:MODE BURS
600 !
```

```
610  !
620  FOR I=1 TO 10
630  WAIT .01                                ! For handshaking compensation. If necessary, use wait
640  !
650  !
660  OUTPUT @Pwr_mtr;TRIG                    ! TRIG is the SCPI Bus trigger. Can also use *TRG
670  WAIT .01                                ! For handshaking compensation. If necessary, use wait
680  OUTPUT @Pwr_mtr;FETC1?                  ! FETC#? acquires data
690  ENTER @Pwr_mtr;Chan1sens_1(*)
700  !ENTER @Pwr_mtr;Chan1sens_1(*),Chan2sens_2(*)
                                           ! Use this line when two sensors are attached.

710  PRINT Chan1sens_1(*)
720  !PRINT Chan1sens_1(*),Chan2sens_2(*)! Use this line when two sensors are attached.
730  PRINT ""
740  NEXT I
750  !
760  END
```

A.5.6 TRIGgering Example 6

Be careful when using BURSt Mode. For example, the user must use INIT:CONT ON; the user does not have manual control of trigger arming sequence using INIT, as the user do using the FETCh#? command with the NORMAl Mode. This is of particular concern using TTL level triggering on either the front panel EXT connector or the VXI backplane TTLT trigger functions. The user must control the triggering through control of the trigger source. The user must use INIT:CONT ON in BURSt Mode; using INIT control arming of the trigger sequence is not allowed.

The following example uses EXTeRnal TTL level triggering using the external trigger input on the front panel of the 58542 VXI Universal Power Meter. Twenty readings are stored in the measurement buffer. Then FETCh#? is used during SWIFt Mode. Please note there is a TTL level hardware handshake capability using the ANALOG OUT BNC connector which is also on the front panel. The Analog BNC will output a high (5V) when the instrument is ready for triggering. After a trigger is received, the Analog BNC output goes low (0V).

TRIG:SOUR HOLD halts the SWIFt Mode triggering sequence.

```
10  ALPHA ON
20  CLEAR SCREEN
30  !
40  OPTION BASE 1
50  DIM Id$(50),Err_msg$(70)
60  DIM Ques$(200),A$(80),Chan1sens_1(20)
70  DIM Chan2sens_2(20)
80  !
90  !
100 !#####
110 !   Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot0 TO 70100           ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101         ! 70101 is Power Meter, in 1st position right of slot 0
150 !#####
160 !
170 !
180 CLEAR @Pwr_mtr
190 WAIT 1
200 OUTPUT @Pwr_mtr;*CLS             ! Clears old messages from SYST:ERR buffer
210 WAIT 0.3
220 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode to perform channel configuration
230 OUTPUT @Pwr_mtr;CALC1:POW 1      ! Channels 1 or 2 can be either POW 1 or POW 2
240                                ! RATio and DIFFerence configurations are illegal in
                                ! SWIFt and BURSt Modes.

250 !
260 !#####
270 !
280 ! Entering SWIFt Mode
290 !
300 OUTPUT @Pwr_mtr;CALC1:MODE SWIF ! Enters SWIFt Mode for fastest individual data point
                                ! triggered measurements.

310 !
320 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.22E8
                                ! Applies Cal Factor in SWIFt mode
330                                ! Can be sent before or after CALC#:MODE SWIF
340 !

350 OUTPUT @Pwr_mtr;TRIG:SOUR EXT   ! TTL level triggering, Each trigger acquires one data
                                ! point in SWIFt Mode.
360                                ! Can be sent before or after CALC#:MODE SWIF
370 !
380 OUTPUT @Pwr_mtr;TRIG:COUN 20    ! Stores 20 points for simultaneous output using
                                ! FETCh#?.
390                                ! Must be sent after CALC#:MODE SWIF
```

```
400  !
410  !
420  FOR I=1 TO 10
430  !WAIT 2                                ! If necessary, use wait
440
450  OUTPUT @Pwr_mtr;FETC1?                ! FETC#? acquires data
460  ENTER @Pwr_mtr;Chan1sens_1(*)
470  !ENTER @Pwr_mtr;Chan1sens_1(*),Chan2sens_2(*)
                                           ! Use this line when two sensors are attached.
480  !
490  PRINT Chan1sens_1(*)
500  !PRINT Chan1sens_1(*),Chan2sens_2(*)    ! Use this line when two sensors are attached.
510      PRINT ""
520  NEXT I
530  !
540  END
```

The fastest SWIFt Mode measurement speeds are achieved with TRIG:SOUR:IMM and TRIG:COUN set to values larger than about 25. See High Speed Measurements in Section A.8 for additional information and examples.

The fastest BURSt Mode measurement speeds are achieved with TRIG:COUN at about 80 and TRIG:DEL 0. See High Speed Measurements in Section for additional information and examples.

A.6 Channel Configuration Examples

A.6.1 Single Sensor Power Measurement

Default definition of software calculation channels 1 and 2 are for sensors 1 and 2, respectively. This configuration allows measurement of the power level incident upon sensor 1 on software configuration channel 1, and measurement of the power level incident upon sensor 2 on software configuration channel 2. Normal Mode and Swift Mode measurements are faster with only one sensor set to STATE ON. Since this is the default configuration, consider turning one channel off occasionally. This will only be necessary when two sensors are attached and both are calibrated. Channel configuration can be changed by sending the CALCulate:RATio or CALCulate:DIFFerence commands.

```
OUTPUT @Pwr_mtr;*RST                ! Configure 58542 to Default Setup
OUTPUT @Pwr_mtr;CALC1?;CALC2?        ! Query channel configuration
ENTER @Pwr_mtr;Chn1_config,Chn2_config
PRINT Chn1_config,Chn2_config
Program Output:                    POW 1  POW 2
```

The following program reverses the default sensor-to-channel assignments.

```
OUTPUT @Pwr_mtr;CALC2:POW 1          ! Configures channel 2 to measure Sensor 1 power
OUTPUT @Pwr_mtr;CALC1:POW 2          ! Configures channel 1 to measure Sensor 2 power
OUTPUT @Pwr_mtr;CALC1?;CALC2?        ! Query channel configuration
ENTER @Pwr_mtr;Chn1_config,Chn2_config
PRINT Chn1_config,Chn2_config
Program Output:                    POW 2  POW 1
```

A.6.2 Ratio Measurement

The CALCulate:RATio command is used to automatically measure the ratio of the power levels incident on the two sensors. Permissible settings are Sensor 1/Sensor 2 & Sensor 2/Sensor 1.

```
OUTPUT @Pwr_mtr;CALC1:RAT 2,1        ! Configures channel 1 to measure Sensor 2 over
                                      ! Sensor 1 power
OUTPUT @Pwr_mtr;CALC2:RAT 1,2        ! Configures channel 2 to measure Sensor 1 over
                                      ! Sensor 2 power
OUTPUT @Pwr_mtr;CALC1?;CALC2?        ! Query channel configuration
ENTER @Pwr_mtr;Chn1_config,Chn2_config
PRINT Chn1_config,Chn2_config
Program Output:                    RAT2,1  RAT1,2
```

A.6.3 Difference Measurement

The CALCulate:DIFFerence command is used to automatically measure the difference of the power levels incident upon the two sensors.

```
OUTPUT @Pwr_mtr;CALC1:DIFF 2,1       ! Configures channel 1 to measure Sensor 2 minus
                                      ! Sensor 1 power
OUTPUT @Pwr_mtr;CALC1?               ! Query Channel 1 configuration
ENTER @Pwr_mtr;Chn1_config
PRINT Chn1_config
Program Output:                    DIFF2,1
```

A.7 Cal Factor Examples

Entering a frequency causes the power meter to use frequency calibration factors which are stored in the power sensor's internal EEPROM. Generally, frequency calibration factors are stored in one gigahertz steps.

Two methods are available for frequency entry. Use SENSE:CORRection:FREQuency to enter a specific carrier frequency, or use SENSE:CORRection:VPROpf to enable the meter's voltage proportional to frequency input BNC (See front panel of the meter).

A.7.1 Cal Factor Example 1

The following program automatically applies the correct cal factor for an 8.23 GHz measurement frequency to the measured data value.

```

310  ASSIGN @Pwr_mtr to 70101
320  CLEAR @Pwr_mtr
330  WAIT 1
350  OUTPUT @Pwr_mtr;CALC1:MODE NORMAL      ! Can ONLY send Cal Factor Correction Commands in
                                           ! Normal Mode!!

360  !
370  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 8.23E9 ! Applies Cal Factor for 8.23 GHz to measurement data.

380  !
400  OUTPUT @Pwr_mtr;MEAS1?                ! Measures Power of 8.23 GHz signal.
410  ENTER @Pwr_mtr;Rdg
420  PRINT Rdg
460  !
470  END

```

A.7.2 Cal Factor Example 2

The following program steps from 1.8 GHz to 2.2 GHz in 10 MHz intervals. The measurement at each step is automatically corrected for cal factor.

```

340  ASSIGN @Pwr_mtr to 70101
350  CLEAR @Pwr_mtr
360  WAIT 1
370  REAL Rdg(41)
380  REAL Frq(41)
390  OUTPUT @Pwr_mtr;CALC1:MODE NORMAL      ! Can ONLY send Cal Factor Correction Commands in
                                           ! Normal Mode!!

400  !
410  FOR I=1 TO 41
420  !
430  Freq=1.8E+9+(I-1)*1.E+7
440  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ;Freq   ! Applies Cal Factor to measurement data.

450  !
460  OUTPUT @Pwr_mtr;MEAS1?
470  ENTER @Pwr_mtr;Rdg(I)
480  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ?      ! Power meter outputs freq setting to confirm command
                                           ! reception.

490  ENTER @Pwr_mtr;Frq(I)
500  NEXT I
510  !
520  PRINT Rdg(*)
530  PRINT Frq(*)
540  !
550  END

```

A.7.3 Cal Factor Example 3

The following program also steps from 1.8 GHz to 2.2 GHz in 10 MHz intervals. The measurement at each step is automatically corrected for cal factor using the V_{PROP} connector on the front panel. In the first part of the program the power meter's V_{PROP} input is configured for compatibility with the Gigatronics Source.

```
340  ASSIGN @Pwr_mtr to 70101
350  CLEAR @Pwr_mtr
360  WAIT 1
370  REAL Rdg(41)
380  OUTPUT @Pwr_mtr;CALC1:MODE NORMAL
                                     ! Can ONLY send VpropF Config. Commands in Normal
                                     ! Mode!!

390  !
400  ! Configure VpropF input for Cal Factor correction
410  !
420  OUTPUT @Pwr_mtr;MEM:SEL VPROPF1    ! Selects memory table for sensor on for editing
430  OUTPUT @Pwr_mtr;MEM:FREQ 0.0       ! Sets freq that corresponds to 0.0V out from source.
440  OUTPUT @Pwr_mtr;MEM:SLOP 0.5E-9    ! Sets the voltage to freq (must be linear) relationship of
                                     ! source's output (V/Hz).

450  !
460  OUTPUT @Pwr_mtr;SENS1:CORR:VPRO ON
                                     ! Turns VpropF on and all other sources of Cal Factor
                                     ! correction OFF

470  !
480  FOR I=1 TO 41
490  !
500  Freq=1.8E+9+(I-1)*1.E+7
510  OUTPUT @Source;CW;Freq;HZ
520  !
530  OUTPUT @Pwr_mtr;MEAS1?
540  ENTER @Pwr_mtr;Rdg(I)
550  NEXT I
560  !
570  PRINT Rdg(*)
580  !
590  END
```

A.7.4 Cal Factor Example 4

The following program shows how to input specific User Calibration Factor during measurement. This is not the same as the special Frequency Cal Factors that can be programmed into the EEPROM. (See Sensor EEPROM Commands in Section 2.5.32 for more information). This technique applies a specific known value during measurements. It is useful when having performed a sensor calibration with other devices attached to the sensor input, such as a power splitter or coupler, but do not want to change or reprogram the CAL factor information inside the power sensor's EEPROM. First the program sets the 58542 to 50 MHz where the Cal Factors of Giga-tronics power sensors are always 0.0 dBm.

```

310  ASSIGN @Pwr_mtr to 70101
320  CLEAR @Pwr_mtr
330  WAIT 1
340  OUTPUT @Pwr_mtr;CALC1:MODE NORMAL
                                     ! Can ONLY send Sensor Offset Commands in
                                     ! Normal Mode!!

350  !
360  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 5E7
                                     ! Cal Factors always 0.00dB at 50 MHz.

370  OUTPUT @Pwr_mtr;SENS1:CORR:OFFS:STAT ON
                                     ! Enables sensor offset control.

380  OUTPUT @Pwr_mtr;SENS1:CORR:OFFS 6.024
                                     ! Enters 6.024 dB as a Sensor Offset

390  !
400  OUTPUT @Pwr_mtr;MEAS1?          ! Measures Power
410  ENTER @Pwr_mtr;Rdg
420  PRINT Rdg
430  !
440  END

```

A.7.5 Cal Factor Example 5

In Burst and Swift Mode, the meter's functionality is restricted to allow the microprocessor to devote most of its operation to performing measurement operations. If measuring a single frequency, this technique will not be need for Burst or Swift Mode data. In Burst or Swift Mode, measurement correction for Cal Factor is always performed with the SENS:CORR:FREQ ### command. By sending this command before entering the Burst or Swift Mode from the Normal mode, all subsequent Burst or Swift Mode measurements will be corrected for that frequency.

The above operation creates a problem if changing frequency during Burst or Swift Mode measurement. The following program is used to apply correct cal factors to swept or multi frequency measurements that have been performed during Burst or Swift Modes. In these modes, swept measurement correction functions are performed in the computer, thus increasing the measurement speed more than would otherwise be possible. First the Cal Factors are read from the sensor's EEPROM. Then the Cal Factors are put through an interpolation algorithm into a correction data array that matches the start/stop frequencies of the test source and the number of measurement points to be collected during measurement. Then measurement is performed, and the correction factor array is added to the measurement data array before being output to a file or swept onto a screen display.

```
10  ALPHA ON
20  CLEAR SCREEN
30  OPTION BASE 1
40  !
50  DIM Freqs(80),Clfcs(80),Corr_clf(5000),Rdgs(5000),Rdgs_corr(5000)
                                         ! These are in REDIMs later in program
60  DIM Id$(90),Err_msg$(70)
70  DIM Ques$(200),Calf$(200)
80  !
90  Tim_per_pnt = 5                      ! milliseconds per sample point. Set 1 to 999.
100 !
110 !#####
120 !      Instrument ADDRESS ALLOCATION
130 !
140 ASSIGN @Slot0 TO 70100              ! 70100 is Logical Address of the Slot 0
                                         ! controller (Resource Manager)
150 ASSIGN @Sweeper TO 720              ! Use normal address for non-VXI instruments
160 ASSIGN @Pwr_mtr TO 70101           ! Power Meter is next to the slot 0 Resource Manager
170 !#####
180 !
190 ! Identify Attached Instruments
200 !
210 OUTPUT @Slot0;*IDN?
220 ENTER @Slot0;Id$
230 PRINT SLOT 0 is ;Id$
240 !
250 OUTPUT @Pwr_mtr;*IDN?
260 ENTER @Pwr_mtr;Id$
270 PRINT SLOT 1 is ;Id$
280 WAIT 1
290 !
300 !#####
310 !
320 ! CALIBRATE THE SENSORS
330 !
340 !#####
350 !
360 CLEAR @Pwr_mtr
370 WAIT 1
380 OUTPUT @Pwr_mtr;CALC1:MODE NORMAL
                                         ! Can ONLY send Sensor Offset
```

```

! Commands in Normal Mode!!
390 !
400 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 5E7
! Cal Factors always 0.00dB at 50MHz

410 !
420 ! Find out the number of Cal Factors in EEPROM
430 ! Include Std Cal Factors at 1 GHz intervals and any special Cal Factors.
440 !
450 OUTPUT @Pwr_mtr;DIAG:SENS1:EEPROM:CALFR?
460 ENTER @Pwr_mtr;Frs_std_freq,Std_freq_step,No_std_freqs,No_spl_freqs
470 ENTER @Pwr_mtr;Frst_std_freq,Std_freq_step,No_std_freqs
480 No_spl_freqs=1 ! Added to correct bug in DIAG:SENS#:EEPROM:CALFR?
490 PRINT Frst_std_freq,Std_freq_step,No_std_freqs,No_spl_freqs
500 !
510 !
520 ! When you query the 58542 for frequencies and Cal Factors there will be
530 ! No_std_freqs + No_spl_freqs = number of items you need to read
540 !
550 No_cal_pnts=No_std_freqs+No_spl_freqs
560 REDIM Freqs(No_cal_pnts),Clfcs(No_cal_pnt)
! Dimension according to number of Cal Factors to be read in.
570 PRINT There are ;No_cal_pnts; of Cal Factors in this sensor.
580 !
590 OUTPUT @Pwr_mtr;SENS1:CORR:EEPROM:FREQ?
! Asks the 58542 for the Frequency array from sensor 1

600 ENTER @Pwr_mtr;Freqs(*)
610 PRINT Freqs(*)
620 !
630 OUTPUT @Pwr_mtr;SENS1:CORR:EEPROM:CALF?
! Asks the 58542 for the Frequency array from sensor 1

640 ENTER @Pwr_mtr;Clfcs(*)
650 PRINT Clfcs(*)
660 !
670 !#####
680 ! Now that all the Cal Factors are loaded with their corresponding frequencies,
690 ! we need to create a table of interpolated Cal Factor points based upon the frequencies used
700 ! and number of measurement points in the test program.
710 !
720 ! First get a couple pieces of necessary information
730 !
740 INPUT Input sweep START frequency in GHz.,Strt_freq
750 INPUT Input sweep STOP frequency in GHz.,Stop_freq
760 INPUT Number of points per sweep. 100 to 400 suggested.,Swep_pnts
770 IF Strt_freq>Stop_freq THEN
780 PRINT Make STOP freq. > START freq.
790 WAIT 1
800 GOTO 740
810 ELSE
820 IF Strt_freq<.051 THEN GOTO 740
830 IF Swep_pnts<1 THEN GOTO 740! You can put additional requirements in this section.
840 END IF
850 Strt_freq=1.E+9*Strt_freq
860 Stop_freq=1.E+9*Stop_fr ! Set units to Hz
870 REDIM Corr_clf(Swep_pnts),Rdgs(Swep_pnts),Rdgs_corr(Swep_pnts)
! Re-sized to match number of measuremen
! points in sweep

880 !
890 ! Interpolation routine creates Cal Factor Correction Table in Clf_corr(*)
900 ! Values are in dB!!!! NOT W linear units
910 !
920 FOR I=1 TO Swep_pnts ! For each point in Clf_corr(*)
930 Rdgs(I)=1

```

```
940      Corr_freq=Strt_freq+(I-1)*(Stop_freq-Strt_freq)/(Sweep_pnts-1)
                                     ! Corr_freq is freq corresponding to Clf_corr(I)
950      FOR K=1 TO No_cal_pnts      ! Find next highest and lowest Cal Factor
                                     ! frequency from Corr_freq
960      IF Freqs(K)>=Corr_freq THEN
970          Next_higher_f=Freqs(K)
980          Next_higher_clf=Clfcs(K)
990          Next_lower_f=Freqs(K-1)
1000         Next_lower_clf=Clfcs(K-1)
1010         K=No_cal_pnts
1020     !
1030     END IF
1040     NEXT K
1050     F_delta_multpl=(Corr_freq-Next_lower_f)/(Next_higher_f-Next_lower_f)
                                     ! Multiplier for next formula
1060     Corr_clf(I)=Next_lower_clf+F_delta_multpl*(Next_higher_clf-Next_lower_clf)
                                     ! Interpolates the Cal Factor Value
1070     PRINT Corr_freq,Corr_clf(I)
1080 NEXT I
1090 !
1100 ! Set the source for swept operation
1110 !
1120 PRINT Configuring Gigatronics 7200 Microwave Sweeper.
1130 OUTPUT @Sweeper,HP              ! Set Giga-tronics 7200 to HP emulation mode
1140 OUTPUT @Sweeper,OPFA;Strt_freq
1150 OUTPUT @Sweeper,OPFB;Stop_freq
1160 OUTPUT @Sweeper;FC;Tim_per_pnt*Sweep_pnts;MS
1170 !
1180 ! Perform Measurement in Burst Mode or Swift Mode for Fast measurements.
1190 ! Shared Variables may include Sweep_pnts and Tim_per_pnt
1200 !
1210 GOSUB Burst_mode_swp              ! Goes to the swept frequency, Burst/Swift Mode Data
                                     ! acquisition subroutine
1220 !
1230 ! Data comes back in from Burst Mode-or Swift Mode-as rdgs(*). Always in log units, dBm.
1240 !
1250 MAT Rdgs_corr=Rdgs+Corr_clf      ! Array math function that adds the measurement
                                     ! data to the cal factor array
1260 !
1270 GOSUB Output_data                ! Output to screen graph, printout, file, etc.....
1280 !
1290 END
```

A.8 High Speed Measurement Examples

A.8.1 High Speed Measurement Example 1

The following program shows the fastest SWIFt Mode measurement speed possible. IMMEDIATE triggering is used to allow the 58542 to trigger a measurement automatically. Be sure to only use one channel defined to one sensor for the fastest speeds.

```

170  ASSIGN @Pwr_mtr to 70101
180  CLEAR @Pwr_mtr
190  WAIT 1
200  OUTPUT @Pwr_mtr;*CLS                ! Clears old messages from SYST:ERR buffer
210  WAIT 0.3
220  OUTPUT @Pwr_mtr;CALC1:MODE NORM    ! NORMAl Mode to perform channel configuration
230  OUTPUT @Pwr_mtr;CALC1:POW 1        ! Channels 1 or 2 can be either POW 1 or POW 2
240                                     ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
250  !
260  !#####
270  !
280  ! Entering SWIFt Mode
290  !
300  OUTPUT @Pwr_mtr;CALC1:MODE SWIF    ! Enters SWIFt Mode for fastest continuous
                                     ! measurements with IMM.
310  !
320  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 16.97E9
                                     ! Applies Cal Factor in SWIFt mode
330                                     ! Can be sent before or after CALC#:MODE SWIF
340  !
350  OUTPUT @Pwr_mtr;TRIG:SOUR IMM
360
370  !
380  !
390  Loopcount=100
400  Time1=TIMEDATE
410  FOR I=1 TO Loopcount
420  OUTPUT @Pwr_mtr;FETC1?            ! FETC#? acquires data
430  ENTER @Pwr_mtr;Chan1sens_1(I)
440  NEXT I
450  Time2=TIMEDATE
460  Time=Time2-Time1
470  Speed=Loopcount/Time              ! Units are readings per second.
480  !
490  PRINT Chan1sens_1(*)
500  PRINT Speed; readings per second.
510  !
520  END

```

A.8.2 High Speed Measurement Example 2

Using one of the slowest system configurations available, external PC controller with GPIB slot 0 resource manager and programming through a very slow Basic program, the previous program achieved a speed of 24 readings per second. With faster systems using embedded PCs and faster software, measurement speeds have been recorded as high as 71 readings per second.

```
10 ALPHA ON
20 CLEAR SCREEN
30 !
40 OPTION BASE 1
50 DIM Id$(50),Err_msg$(70)
60 DIM Ques$(200),A$(80),Chan1sens_1(200)
70 DIM Chan2sens_2(200)
80 Counter=1
90 !
100 !#####
110 ! Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot0 TO 70100 ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101 ! 70101 is Power Meter in 1st position right of slot 0
150 !#####
160 !
180 !
290 CLEAR @Pwr_mtr
300 WAIT 1
310 OUTPUT @Pwr_mtr;*CLS ! Clears old messages from SYST:ERR buffer
320 WAIT 0.3
330 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode to perform channel configuration
340 OUTPUT @Pwr_mtr;CALC1:POW 1 ! Channels 1 or 2 can be either POW 1 or POW 2
350 ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
370 !
380 !#####
390 !
400 ! Entering SWIFt Mode
410 !
420 OUTPUT @Pwr_mtr;CALC1:MODE SWIF ! Enters SWIFt Mode for fastest continuous
! measurements with IMM.
430 !
440 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 16.97E9
! Applies Cal Factor in SWIFt mode
! Can be sent before or after CALC#:MODE SWIF
450
460 !
470 OUTPUT @Pwr_mtr;TRIG:SOUR IMM! IMM triggering is illegal in SWIFt Mode, Use BUS or EXT.
480 ! Can be sent before or after CALC#:MODE SWIF
490 !
610 !
611 Loopcount=50
613 Time1=TIMEDATE
620 FOR I=1 TO Loopcount
670 !OUTPUT @Pwr_mtr;FETC1? ! FETC#? acquires data
671 OUTPUT @Pwr_mtr;FETC1?;FETC2? ! Use this line when two sensors are attached.
680 !ENTER @Pwr_mtr;Chan1sens_1(I)
681 ENTER @Pwr_mtr;Chan1sens_1(I),Chan2sens_2(I) ! Use this line when two sensors are attached.
730 NEXT I
731 Time2=TIMEDATE
733 Time=Time2-Time1
743 Speed=Loopcount/Time ! Units are readings per second.
753 !
763 !PRINT Chan1sens_1(*)
773 PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
783 !PRINT Speed; readings per second.
784 PRINT Speed; readings per second per channel.
793 !
803 END
```

A.8.3 High Speed Measurement Example 3

Using the same system configuration, the previous program achieved a speed of 25 readings per second per channel. With faster systems using embedded PCs and faster software, measurement speeds have been recorded as high as 71 readings per second.

The following program shows fast BUS triggering in the SWIFt Mode. TRIG (or *TRG) is used to acquire data, and FETCh#? processes and outputs the data to the slot 0 controller/resource manager. This program does not use the meter's data buffering capability.

```

170  ASSIGN @Pwr_mtr to 70101
180  CLEAR @Pwr_mtr
190  WAIT 1
200  OUTPUT @Pwr_mtr;*CLS           ! Clears old messages from SYST:ERR buffer
205  WAIT 0.3
210  PRINT Running...
220  !
230  OUTPUT @Pwr_mtr;CALC1:MODE NORM      ! NORMal Mode to perform channel configuration
240  OUTPUT @Pwr_mtr;CALC1:POW 1          ! Channels 1 or 2 can be either POW 1 or POW 2
250                                     ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
260  !
270  !#####
280  !
290  ! Entering SWIFt Mode
300  !
310  OUTPUT @Pwr_mtr;CALC1:MODE SWIF      ! Enters SWIFt Mode for fastest individual data point
                                         ! triggered measurements.
320  !
330  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.44E9
                                         ! Applies Cal Factor in SWIFt mode
                                         ! Can be sent before or after CALC#:MODE SWIF
340                                     !
350  !
360  OUTPUT @Pwr_mtr;TRIG:SOUR BUS        ! BUS or EXT triggering is slower than IMM
370                                     ! Can be sent before or after CALC#:MODE SWIF
380  !
390  FOR I=1 TO 10
400      FOR K=1 TO 20
410          OUTPUT @Pwr_mtr;TRIG          ! TRIG is the SCPI Bus trigger. Can also use *TRG
420          OUTPUT @Pwr_mtr;FETC1?        ! FETC#? acquires data
430          ENTER @Pwr_mtr;Chan1sens_1(K)
440          !ENTER @Pwr_mtr;Chan1sens_1(K),Chan2sens_2(K)
                                         ! Use this line when two sensors are attached.
450      NEXT K
460      !
470          PRINT Chan1sens_1(*)
480          !PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
490          PRINT ""
500      NEXT I
510      !
520  END

```

A.8.4 High Speed Measurement Example 4

The following program shows SWIFt Mode measurements using EXT TTL triggering and Buffered data. INIT:CONT must be set to ON; The user can not use INIT with INIT:CONT set to OFF. This program buffers 30 measurements in the 58542 before group download to the controller using the TRIG:COUN command in line 390. In the SWIFT mode, this command must be sent after the TRIG:SOUR command.

```
170 ASSIGN @Pwr_mtr to 70101
180 CLEAR @Pwr_mtr
190 WAIT 1
200 OUTPUT @Pwr_mtr;*CLS ! Clears old messages from SYST:ERR buffer
210 WAIT 0.3
220 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMAl Mode to perform channel configuration
230 OUTPUT @Pwr_mtr;CALC1:POW 1 ! Channels 1 or 2 can be either POW 1 or POW 2
240 ! RAtio and DIFFerence configurations are illegal in
! SWIFt and BURSt Modes.

250 !
260 !#####
270 !
280 ! Entering SWIFt Mode
290 !
300 OUTPUT @Pwr_mtr;CALC1:MODE SWIF ! Enters SWIFt Mode for fastest individual data point
! triggered measurements.

310 !
320 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.22E8
! Applies Cal Factor in SWIFt mode
330 ! Can be sent before or after CALC#:MODE SWIF
340 !
350 OUTPUT @Pwr_mtr;TRIG:SOUR EXT ! TTL level triggering, Each trigger acquires one
! data point in SWIFt Mode.
360 ! Can be sent before or after CALC#:MODE SWIF
370 !
380 Num_pts=30
390 OUTPUT @Pwr_mtr;TRIG:COUN;Num_pts ! Stores 20 points for simultaneous output using FETCh#?.
400 ! Must be sent after CALC#:MODE SWIF
410 !
420 REDIM Chan1sens_1(Num_pts),Chan2sens_2(Num_pts)
430 !
440 Time1=TIMEDATE
450 WAIT 5 ! If necessary, use wait statements
460 ! For example, use it if TRIG:COUN # is high or TTL
! trigger source is slow.

470 OUTPUT @Pwr_mtr;FETC1? ! FETC#? acquires data
480 !OUTPUT @Pwr_mtr;FETC1?;FETC2?
490 ENTER @Pwr_mtr;Chan1sens_1(Num_pts)
500 !ENTER @Pwr_mtr;Chan1sens_1(Num_pts),Chan2sens_2(Num_pts)
! Use this line when two sensors are attached.

510 Time2=TIMEDATE
520 Time=Time2-Time1
530 Speed=Num_pts/Time
540 !
550 PRINT Chan1sens_1(*)
560 !PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
570 PRINT Speed; readings per second.
580 PRINT ""
590 !
600 END
```

A.8.5 High Speed Measurement Example 5

The following program uses BURSt Mode for the fastest measurement rates possible. The maximum measurement speed is performed when TRIG:DEL is set to 0. TRIG:DEL controls the speed of sampling and data buffering. When TRIG:DEL is set to 0.004, samples will be taken every 4 milliseconds, on both channels if connected, and stored in the meter's internal data buffer. This speed does not control or account for the meter's internal data processing time after data acquisition or the speed of data transfer to the controller. This second component of time, the time to get data from the 58542, is proportional to the number of data points measured. Therefore, the example below uses only one channel and keeps the number of points buffered to a minimum.

Both channels' data will be taken at the same time during BURSt Mode. Power meter measurement speed does not change when two sensors are connected versus only one sensor. However, the 58542 processing time and the time to transmit the data over the VXI and GPIB interfaces takes longer due to the additional sensor data. If two sensors are connected, calibrated, and their respective channels are set to ON, then read both arrays of data. Only read one array of data when one sensor is attached, calibrated, and set to ON.

As shown in the examples, send the CALC#:MODE BURS command prior to sending the BURSt Mode configuration commands TRIG:SOUR, TRIG:MODE, TRIG:COUN, and TRIG:DEL.

```

10  ALPHA ON
20  CLEAR SCREEN
30  !
40  OPTION BASE 1
50  DIM Id$(50),Err_msg$(70)
60  DIM Ques$(200),A$(80),Chan1sens_1(500)
70  DIM Chan2sens_2(500)
80  !
90  !
100 !#####
110 ! Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot 0 TO 70100           ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101         ! 70101 is Power Meter in 1st position of slot 0
150 !#####
160 !
170 ! Identify Attached Instruments
180 !
190 OUTPUT @Slot0;*IDN?
200 ENTER @Slot0;Id$
210 PRINT SLOT 0 is ;Id$
220 !
230 OUTPUT @Pwr_mtr;*IDN?
240 ENTER @Pwr_mtr;Id$
250 PRINT SLOT 1 is ;Id$
260 WAIT 1
270 !
280 !
290 CLEAR @Pwr_mtr
300 WAIT 1
310 OUTPUT @Pwr_mtr;*CLS             ! Clears old messages from SYST:ERR buffer
320 WAIT 0.3
330 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! NORMal Mode to perform channel configuration
340 OUTPUT @Pwr_mtr;CALC1:POW 1      ! Channels 1 or 2 can be either POW 1 or POW 2
350                                ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
360 OUTPUT @Pwr_mtr;TRIG:SOUR IMM    ! IMM set here to highlight conflict with BURSt operation
370 !
380 !#####
390 !

```

58542 VXIbus Universal Power Meter

```
400 ! Entering BURSt Mode
410 !
420 OUTPUT @Pwr_mtr;CALC1:MODE BURS ! Enters BURSt Mode for fastest measurement speeds.
430 !
440 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.44E9
! Applies Cal Factor in BURSt mode
450 ! Can be sent before or after CALC#:MODE BURS
460 !
470 OUTPUT @Pwr_mtr;TRIG:SOUR BUS ! IMM triggering is illegal in BURSt Mode, Use BUS or
! EXT.
480 ! Can be sent before or after CALC#:MODE BURS
490 !
500 OUTPUT @Pwr_mtr;TRIG:MODE POST ! Data acquired after trigger, not before as with PRE.
510 ! Send only after CALC#:MODE BURS
520 !
530 OUTPUT @Pwr_mtr;TRIG:COUN 500 ! 500 readings acquired and stored with each trigger.
540 ! Send only after CALC#:MODE BURS, following
! TRIG:MODE.
550 ! Be sure COUN# matches ENTER variable dimension.
560 !REDIM Chan1sens_1(500),Chan2sens_2(500) ! REDIM to smaller array size only if necessary.
570 !
580 OUTPUT @Pwr_mtr;TRIG:DEL .000 ! 0 millisecond between rdgs setting is 5100 rdgs/sec.
590 ! Send only after CALC#:MODE BURS, following
! TRIG:COUN.
600 !
610 !
620 FOR I=1 TO 10
630 Time1=TIMEDATE
640 !
650 OUTPUT @Pwr_mtr;TRIG ! TRIG is the SCPI Bus trigger. Can also use *TRG
660 OUTPUT @Pwr_mtr;FETC1? !FETC#? acquires data
670 ENTER @Pwr_mtr;Chan1sens_1(*)
680 !ENTER @Pwr_mtr;Chan1sens_1(*),Chan2sens_2(*)
! Use this line when two sensors are attached.
690 !
700 Time2=TIMEDATE
710 Time=Time2-Time1
720 Speed=500/Time
730 PRINT Chan1sens_1(*)
740 !PRINT Chan1sens_1(*),Chan2sens_2(*) ! Use this line when two sensors are attached.
750 PRINT Speed; readings per second, round trip.
760 PRINT ""
770 NEXT I
780 !
790 END
```

A.8.6 High Speed Measurement Example 6

The preceding program performed 500 measurements at a rate of 5100 per second then processed and output the data to the controller. Round trip speed was between 120 and 140 per second. Using 100 measurements per BURSt instead of 500, the round trip speed was 100 to 115 per second.

The following example is similar to the previous program except for the use of EXT triggering to initiate the BURSt measurement.

```

10  ALPHA ON
20  CLEAR SCREEN
30  !
40  OPTION BASE 1
50  DIM Id$(50),Err_msg$(70)
60  DIM Ques$(200),A$(80),Chan1sens_1(500)
70  DIM Chan2sens_2(500)
80  !
90  !
100 !#####
110 !      Instrument ADDRESS ALLOCATION
120 !
130 ASSIGN @Slot0 TO 70100          ! 70100 is Logical Address of the Slot 0 controller
140 ASSIGN @Pwr_mtr TO 70101        ! 70101 is Power Meter in 1st position right of slot 0
150 !#####
160 !
170 ! Identify Attached Instruments
180 !
190 OUTPUT @Slot0;*IDN?
200 ENTER @Slot0;Id$
210 PRINT SLOT 0 is ;Id$
220 !
230 OUTPUT @Pwr_mtr;*IDN?
240 ENTER @Pwr_mtr;Id$
250 PRINT SLOT 1 is ;Id$
260 WAIT 1
270 !
280 !
290 CLEAR @Pwr_mtr
300 WAIT 1
310 OUTPUT @Pwr_mtr;*CLS          ! Clears old messages from SYST:ERR buffer
320 WAIT 0.3
330 OUTPUT @Pwr_mtr;CALC1:MODE NORM ! Normal Mode to perform channel configuration
340 OUTPUT @Pwr_mtr;CALC1:POW 1    ! Channels 1 or 2 can be either POW 1 or POW 2
350                                ! RAT and DIFF are illegal in SWIFt and BURSt Modes.
360 !
370 !#####
380 !
390 ! Entering BURSt Mode
400 !
410 OUTPUT @Pwr_mtr;CALC1:MODE BURS ! Enters BURSt Mode for fastest measurement speeds.
420 !
430 OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 2.44E9
440                                ! Applies Cal Factor in burst mode
450                                ! Can be sent before or after CALC#:MODE BURS
460 OUTPUT @Pwr_mtr;TRIG:SOUR EXT  ! EXT TTL Level input begins BURSt Mode measure-
ment.                               ! Can be sent before or after CALC#:MODE BURS
470                                !
480 !
490 OUTPUT @Pwr_mtr;TRIG:MODE POST ! Data acquired after trigger, not before as with PRE.
500                                ! Send only after CALC#:MODE BURS
510 !
520 OUTPUT @Pwr_mtr;TRIG:COUN 500  ! 500 readings acquired and stored with each trigger.
530                                ! Send only after CALC#:MODE BURS, following

```

58542 VXibus Universal Power Meter

```
TRIG:MODE
540                                     ! Be sure COUN# matches ENTER variable dimension.
550 !REDIM Chan1sens_1(500),Chan2sens_2(500) ! REDIM to smaller array size only if necessary.
560 !
570 OUTPUT @Pwr_mtr;TRIG:DEL .000      ! 0 millisecond between rdgs setting is 5100 rdgs/sec.
580                                     ! Send only after CALC#:MODE BURS, following TRIG:COUN.
590 !
600 !
610 FOR I=1 TO 10
620 !WAIT .01                          ! Wait for trigger compensation. If necessary, use wait statements
630
640
650 Time1=TIMEDATE
660 !
670 OUTPUT @Pwr_mtr;FETC1?             ! FETC#? acquires data
680 WAIT 2                             ! for POST triggering
690 ENTER @Pwr_mtr;Chan1sens_1(*)
700 !ENTER @Pwr_mtr;Chan1sens_1(*),Chan2sens_2(*)
                                     ! Use this line when two sensors are attached.
710 !
720 Time2=TIMEDATE
730 Time=Time2-Time1
740 Speed=500/Time
750 PRINT Chan1sens_1(*)
760 !PRINT Chan1sens_1(*),Chan2sens_2(*)! Use this line when two sensors are attached.
770     PRINT Speed; readings per second, round trip.
780     PRINT ""
790 NEXT I
800 !
810 END
```

The preceding program performs measurement at approximately 5100 measurements per second. Assuming pretriggering during the PRINT statements, a round trip speed of 180 to 195 measurements per second was achieved.

A.9 Relative or Referenced Measurement Examples

A.9.1 Relative or Referenced Measurements Example 1

The following program automatically sets a power level reference when the computer's ENTER key is actuated. From that point forward the power level - relative to the power level at the time the ENTER key was actuated - is monitored and displayed with minimum and maximum values since the reference was set.

```

290 ASSIGN @Pwr_mtr to 70101
300 CLEAR @Pwr_mtr
310 WAIT 1
320 !
330 OUTPUT @Pwr_mtr;CALC1:MODE NORMAL! Can ONLY use REFERENCE commands in NORMAl Mode!!
340 OUTPUT @Pwr_mtr;CALC2:POW 2 ! Channel 2 configured to measure sensor 2 power
350 !
360 OUTPUT @Pwr_mtr;TRIG:SOUR IMM ! TRIG:SOUR must be IMM when using READ#?
370 OUTPUT @Pwr_mtr;INIT:CONT OFF ! INITiate:CONTinuous arming must be OFF when using
    ! READ#?
380 !
390 OUTPUT @Pwr_mtr;SENS2:AVER:COUN 1 ! Sets averaging to manual and one sample per
    ! measurement reading.
400 !
410 OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 17.4E9
    ! Applies Cal Factor for 17.4 GHz to measurement data.
420 !
430 !#####
440 !
450 ! Relative measurement setup using CALC#:REF:COLL.
460 !
470 OUTPUT @Pwr_mtr;CALC2:REF:MAG 0.00 ! Resets REFERENCE level from value set with
    CALC2:REF:COLL
480 OUTPUT @Pwr_mtr;CALC2:REF:STAT ON ! Enables REFERENCE operation.
490 !
500 INPUT Press ENTER key to set to 0.0dB reference operation,Dmy
510 OUTPUT @Pwr_mtr;CALC2:REF:COLL ! Takes current measurement and adds inverse to further
    ! measurements
520 !
530 ! Setup power meters' MIN and MAX monitors
540 !
550 OUTPUT @Pwr_mtr;CALC2:MIN:STAT ON
560 OUTPUT @Pwr_mtr;CALC2:MAX:STAT ON
570 !
580 PRINT Power Variation, Largest Min, Largest Max.
590 WHILE Cont_meas=1
600     OUTPUT @Pwr_mtr;MEAS2? ! Measures Power at sensor.
610     ENTER @Pwr_mtr;Rdg
620     !
630     OUTPUT @Pwr_mtr;CALC2:MIN? ! Grabs minimum since CALC2:MIN:STAT ON
640     ENTER @Pwr_mtr;Min
650     OUTPUT @Pwr_mtr;CALC2:MAX? ! Grabs maximum since CALC2:MAX:STAT ON
660     ENTER @Pwr_mtr;Max
670     PRINT Rdg,"",Min,"",Max
680     END WHILE
690 !
890 END

```

A.9.2 Relative or Referenced Measurements Example 2

The following program finds the 1 dB compression of an amplifier/transmitter at a single frequency.

```
300  ASSIGN @Pwr_mtr to 70101
310  CLEAR @Pwr_mtr
320  WAIT 1
330  !
340  OUTPUT @Pwr_mtr;CALC1:MODE NORMAL          ! Can ONLY use REFerence commands in NORMAl

Mode!!
350  OUTPUT @Pwr_mtr;CALC1:POW 1                ! Channel 1 configured to measure sensor 1 power
360  OUTPUT @Pwr_mtr;CALC1:UNIT W              ! Transmitter output power in Watts.
370  OUTPUT @Pwr_mtr;CALC2:RAT 1,2             ! Transmitter gain stays in default, dBm.
380  OUTPUT @Pwr_mtr;CALC2:UNIT DBM            ! Transmitter output power in Watts. Units are channel,
                                              ! not sensor, specific

390  !
400  !
410  OUTPUT @Pwr_mtr;TRIG:SOUR IMM ! TRIG:SOUR must be IMM when using READ#?
420  OUTPUT @Pwr_mtr;INIT:CONT OFF ! INITiate:CONTinuous arming must be OFF when using READ#?
430  !
440  OUTPUT @Pwr_mtr;SENS1:AVER:COUN 1! Sets averaging to manual and one sample per measurement
    reading.
450  OUTPUT @Pwr_mtr;SENS2:AVER:COUN 4! Sets averaging to manual and 4 samples per measurement
    reading.
460  !
470  OUTPUT @Pwr_mtr;SENS1:CORR:FREQ 1.94E9
                                              ! Applies Cal Factor for 1.94 GHz, Sensor 1.
480  OUTPUT @Pwr_mtr;SENS2:CORR:FREQ 7.0E7
                                              ! Applies Cal Factor for 70 MHz IF input, Sensor 2.

490  !
500  !#####
510  !
520  ! System Setup
530  ! Power Splitter attached to source.
540  ! DUT input and sensor 2 on the splitter outputs.
550  ! Sensor 1 at DUT output.
560  ! Check max power rating on sensor 1 and use an appropriate attenuator if necessary.
570  ! Use offset to account for any necessary attenuation when not using Giga-tronics high power sensors.
580  !
590  !#####
600  !
610  ! Relative measurement setup using CALC#:REF:COLL.
620  !
630  OUTPUT @Pwr_mtr;CALC2:REF:MAG 0.00        ! Resets REFerence level from value set with
CALC2:REF:COLL
640  OUTPUT @Pwr_mtr;CALC2:REF:STAT ON        ! Enables REFerence operation.
650  !
660  Smal_sig_pwr=-30
670  OUTPUT @Source;OPPL;Smal_sig_pwr         ! Set power to small signal region of amp, -30 dBm.
680  OUTPUT @Pwr_mtr;CALC2:REF:COLL           ! Takes current measurement and adds inverse to further
                                              ! measurements

690  !
700  ! STEP POWER FROM SMALL SIGNAL REGION TO ABOVE 1 dB COMPRESSION LEVEL
710  !
720  FOR I=Smal_sig_pwr TO Smal_sig_pwr+40 STEP .05
730      OUTPUT @Source;OPPL;I                ! Increments power level into amplifier's input. Add wait statement
                                              ! at 735 if source settles too slow.
740  OUTPUT @Pwr_mtr;READ2?                   ! Measures Sensor 1 over sensor 2, dB relationship
750  ENTER @Pwr_mtr;Rdg
760  PRINT Rdg
770  !
780  Comp_lvl=-1
790  IF Rdg<Comp_lvl THEN                     ! Finds 1 dB compression level
800  OUTPUT @Pwr_mtr;READ1?                   ! Measures Output Power at sensor 1.
```

```
810 ENTER @Pwr_mtr;Rdg
820 PRINT 1 dB Compression level is ;Rdg; Watts, Output Power.
830 GOSUB End
840     END IF
850 NEXT I
860 !
1060 End: !
1070 END
```

A.10 SRQ Interrupt Examples

```
10  ASSIGN @Pwr_mtr to 70101          ! Set GPIB address
20  DIM Buf$(100)                     ! Define data buffer
30  ON INTR 7 GOSUB Srq_isp            ! Assign interrupt service function
40  ENABLE INTR 7;2                    ! enable interrupt
50  !
60  CLEAR @Pwr_mtr                     ! Reset instrument
70  WAIT 1
80  OUTPUT @Pwr_mtr;*CLS                ! Clear interface and output queue
90  WAIT 0.3
100 !
110 OUTPUT @Pwr_mtr;*ESE 1              ! Enable OPC bit
120 OUTPUT @Pwr_mtr;STAT:OPER:ENAB 7712 ! Enable channel 1 & 2 limit and trigger wait mask
130 !
140 Srq_flag=0                         ! Reset task done flag
150 OUTPUT @Pwr_mtr;CAL1:ZERO?;*OPC    ! Zero sensor 1
160 WHILE Srq_flag = 0                 ! Wait until it is done
170     END WHILE
180 ENTER @Pwr_mtr;Result               ! Read zero result
190 IF Result = 0 THEN PRINT Zero is good
200     ELSE
210     PRINT Zero is no good
220     END IF
230 ENTER @Pwr_mtr;Esr_val              ! Read ESR status
240 !
250 Srq_flag = 0                       ! Reset task done flag
260 Meas_flag = 0                       ! Reset measurement flag
270 OUTPUT @Pwr_mtr;MEAS1?;*OPC        ! Measure channel 1 data
280 WHILE Srq_flag = 0                 ! Wait until it is done
290     END WHILE
300 IF Meas_flag = 0 THEN               ! If data is not read
310     ENTER @Pwr_mtr;Result           ! Read measurement data
320     END IF
330     ENTER @Pwr_mtr;Esr_val          ! Read ESR status
340 !
350 STOP
360 !
370 Srq_isp:
380 State = SPOLL(@Pwr_mtr)             ! Serial poll
390 !
400 IF BIT(State,3) THEN                ! Error bit
410     OUTPUT @Pwr_mtr;SYST:ERR?       ! Query error message
420     ENTER @Pwr_mtr;Buf$             ! Read in
430     PRINT Error:;Buf$               ! Print out message
440     END IF
450 !
460 IF BIT(State,7) THEN                ! OSB bit
470     !
480     IF BIT(State,4) THEN             ! MAV bit
490     ENTER @Pwr_mtr;Result           ! Query measurement data
500     Meas_flag = 1                   ! Set data read flag
510     END IF
520 !
530 OUTPUT @Pwr_mtr;STAT:OPER?          ! Query operation status register
540 ENTER @Pwr_mtr;Status
550 PRINT OSB;Status
560 IF BIT(Status,5) THEN PRINT Swift/Burst trigger ready
570 IF BIT(Status,8) THEN PRINT Channel 1 lower limit
580     IF BIT(Status,9) THEN PRINT Channel 1 upper limit
590     IF BIT(Status,10) THEN PRINT Channel 2 lower limit
600     IF BIT(Status,11) THEN PRINT Channel 2 upper limit
610     END IF
620 !
```

```
630 IF BIT(State,5) THEN           ! ESR bit
640     OUTPUT @Pwr_mtr;*ESR?      ! Reset event status register
650     END IF
660 !
670 Srq_flag = 1                   ! Set task done flag
680 ENABLE INTR 7;2
690 RETURN
860 END
```

A.11 Instrument & Sensor Identification Examples

A.11.1 Instrument Identification

The following example reads manufacturer identification, model number and software version number. Software version number is important for troubleshooting and factory technical support. Make sure user or users can identify the software version when requesting technical support.

```
10  ALPHA ON
20  DIM ID$(60),Mfgr$(12)
    ! FOR INSTRUMENT ID VIEWING AT START UP
30  !
40  CLEAR SCREEN
50  !
60  !#####
70  ! Instrument ADDRESS ALLOCATION
80  !
90  ASSIGN @Slot0 TO 70100          ! 70200 is Logical Address of the Slot 0 controller
100 ASSIGN @Pwr_mtr TO 70101       ! Default Power Meter Address of 255 allows VXI dynamic
110                                ! address configuration
120 !
130 !#####
140 !
150 OUTPUT @Slot0;*IDN?
160 ENTER @Slot0;Id$
170 PRINT SLOT 0 is ;Id$
180 !
190 OUTPUT @Pwr_mtr;*IDN?
200 ENTER @Pwr_mtr;Mfgr$,Model,No,Software_ver
    ! DIM Mfgr$ to 12 characters
210 PRINT A;Mfgr$; model;Model;with software version;Software_ver;is installed in slot 1.
211 !
212 ! Main Measurement Loop Start.
```

Instrument identification can be read as a single string as is done in lines 150 to 170 above. Sometimes, however, it is more convenient to read these four items separately for use in comment statements or as identifiers for selecting special command libraries or subroutines.

A.11.2 Sensor Model Identification

A simple method of separating the manufacturer sub-string from the three following numeric items requires reading the manufacturer alphabetical letters into a string variable of limited size. Use a DIM or a REDIM statement to limit size to 12 characters. Thus Model and Software Version can easily be read into numeric variables. No is always 0; it is placed in the *IDN? command output as called for by the IEEE 488.2 Standard. The 58542 can not report it's serial number - which is printed on a label positioned on the side of the instrument - over the bus. If preferred, there is space on the 58542's front panel for the serial number label. The factory will place it there upon request.

The following example reads the model number and serial number of the power sensor currently in use. What does currently in use mean? It means that this was the last sensor connected to this meter input. It does not mean that the sensor is currently attached or that the sensor is calibrated. For in-program checking for sensor attachment or completed power sweep calibration, see the Error Control Examples in Section A.3.3 or the Reading Power Measurements in Section A.4. By operating in this manner, if preferred use a simple WHILE/UNTIL loop in the program to detect when the operator connects the correct power sensor.

Tracking the model number allows the user to be sure that a sensor is being used which is appropriate for measurement application. For example, some user measurement routines may require the use of Peak Power Sensors rather than CW Power Sensor or use of high power sensors rather than standard sensors. The user's program can automatically check for the appropriate sensor and prompt to Please connect Giga-tronics Sensor model #####, if necessary.

```

240  !
250  GOSUB Pwr_amp_test
260  !
270  GOSUB Store_results
280  !
290  END LOOP                      ! Return to beginning of main program.
300  !
310  Pwr_amp_test:                 ! Output is 30 to 40 Watts, TOO HIGH for Standard Sensors
320  !
330  Req_d_snsr1_md1=80355         ! Actual 50W Peak Power Sensor model is 80355A.
340                               ! The A is ignored in Gigatronics software to simplify programs like
                               ! this one.
350  Req_d_snsr2_md1=80350         ! Standard 80350A Peak Power Sensor on input
360  !
370  !
380
!#####
390  !
400  ! Read and compare sensors for correct model number
410  !
420  OUTPUT @Pwr_mtr;SENS1:CORR:EEPROM:TYPE?
                               ! responds with model and serial numbers
430  ENTER @Pwr_mtr;New_snsr1_model,New_snsr1_serno
440  OUTPUT @Pwr_mtr;SENS1:CORR:EEPROM:TYPE?
                               ! responds with model and serial numbers
450  ENTER @Pwr_mtr;New_snsr1_model,New_snsr1_serno
460  !
470  IF Req_d_snsr1_md1=New_snsr1_model THEN
480  ELSE
490  PRINT The amplifier's high power output must be attenuated for this test.,
500  PRINT Connect a Gigatronics model;Req_d_snsr1_md1;to the channel 1 power sensor cable.,
510  INPUT Then press ENTER,Dmy
520  PRINT""
530  GOSUB Pwr_swp_call
540  END IF
550  !
560  IF Req_d_snsr2_md1=New_snsr2_model THEN
570  ELSE

```

58542 VXibus Universal Power Meter

```
580 PRINT Connect a Gigatronics model;Reqd_snsr2_mdl;to the channel 2 power sensor cable.,
590 INPUT Then press ENTER,Dmy
600 GOSUB Pwr_swp_cal2
610 END IF
620 !
630 GOSUB Compare_serno           ! Calibrates sensors, if necessary. SEE next example
640 !
650 GOSUB Gain_tst               ! Configures and performs amplifier gain test.
660 GOSUB Onedb_comp_tst        ! Configures and performs amplifier 1 dB compression test.
670 !
680 RETURN
690 !
700 Pwr_swp_cal:                ! Power Sweep Calibration calibrates the sensor to the meter.
710 !
```

A.11.3 Sensor Serial Number Identification

Tracking sensor serial numbers is important. Measurements cannot be performed unless the sensor has been calibrated to the meter using the built-in power sweep calibrator: this ensures that measurements will never be performed with an uncalibrated sensor. The Giga-tronics 58542 tracks this requirement by reading the sensor's serial number. Thus, by reading in the sensor's serial number at the beginning of measurement subroutines, the user can automatically determine whether or not power sweep calibration is required. This is illustrated in the following example.

```

990      Compare_serno: !
995      !
1000     !#####
1010     !
1020     ! This program identifies sensors by their serial number
1030     ! and jumps to a calibration subroutine if it is a new sensor.
1040     !
1050     !#####
1060     !
1070     ! Sensor Identification routine at beginning of measurement sequence.
1080     ! New sensors will not operate unless they pass calibration first.
1090     !
1100     OUTPUT @Pwr_mtr;SENS1:CORR:EEPROM:TYPE?
1110     ENTER @Pwr_mtr;New_snsr1_model,New_snsr1_serno
1120     OUTPUT @Pwr_mtr;SENS2:CORR:EEPROM:TYPE?
1130     ENTER @Pwr_mtr;New_snsr2_model,New_snsr2_serno
1140     !
1150     IF Old_snsr1_serno=New_snsr1_serno THEN
1160     !
1170     ELSE
1180     GOSUB Pwr_swp_cal1                                ! New Sensor 1, Must Calibrate To the Meter
1190     END IF
1200     !
1210     IF Old_snsr2_serno=New_snsr2_serno THEN
1220     !
1230     ELSE
1240     GOSUB Pwr_swp_cal2                                ! New Sensor 2, Must Calibrate To the Meter
1250     END IF
1260     !
1270     ! Concludes Sensor Serial Number Comparison
1280     ! Use a similar routine when a particular sensor model is required.
1290     ! To do both: Nest an IF-THEN for model # ahead of GOSUB
                                                    ! Pwr_swp_cal#.
1300     !
1310     !#####
1320     !
1330     ! Main loop
1340     !
1350     OUTPUT @Pwr_mtr;SENS1:AVER:TCON:MOV
            ! MOV, Average new sample with previous samples
1360     OUTPUT @Pwr_mtr;SENS2:AVER:TCON:MOV
            ! MOV, Average new sample with previous samples
1370     !
1380     LOOP
1390     OUTPUT @Pwr_mtr;MEAS1?
            ! TRIGGER AND READ CHANNEL 1
1400     ENTER @Pwr_mtr;MEAS1
1410     PRINT CHANNEL 1 IS ;Meas1;dBm.
1420     !
1430     OUTPUT @Pwr_mtr;MEAS2?                ! TRIGGER AND READ CHANNEL 2
1440     ENTER @Pwr_mtr;Meas2
1450     PRINT CHANNEL 2 IS ;Meas2;dBm.
1460     END LOOP
1470     !
1480     !#####

```

58542 VXibus Universal Power Meter

```
1490 !
1500 ! SUBROUTINES
1510 !
1520 !
1530 Pwr_swp_cal1: ! Calibrates Sensor 1 Power Sweep Calibration calibrates the
! sensor to the meter.
1540 !
1541 PRINT Calibrating.....
1550 OUTPUT @Pwr_mtr;CAL1? ! Starts Calibration and delivers a pass/fail flag
1560 ENTER @Pwr_mtr;Pass_cal
1570 IF Pass_cal=0 THEN
1580 PRINT Calibration Passed
1590 Old_snsr1_model=New_snsr1_model
1600 Old_snsr1_serno=New_snsr1_serno
1610 ELSE
1620 PRINT Calibration FAILED, Sensor 1 Attached To Calibrator?
1630 WAIT 10 ! Wait for Operator to attach sensor
1640 GOTO Pwr_swp_cal1
1650 END IF
1660 RETURN
1670 !
1680 Pwr_swp_cal2:! Calibrates Sensor 2
1690 !
1691 PRINT Calibrating.....
1700 OUTPUT @Pwr_mtr;CAL2? ! Starts Calibration and delivers a pass/fail flag
1710 ENTER @Pwr_mtr;Pass_cal
1720 IF Pass_cal=0 THEN
1730 PRINT Calibration Passed
1740 Old_snsr2_model=New_snsr2_model
1750 Old_snsr2_serno=New_snsr2_serno
1760 ELSE
1770 PRINT Calibration FAILED, Sensor 2 Attached To Calibrator?
1780 WAIT 10 ! Wait for Operator to attach sensor
1790 GOTO Pwr_swp_cal2
1800 END IF
1810 RETURN
1940 END
```

Power Sensors

B.1 Introduction

This appendix contains the selection, specifications and calibration data for power sensors used with Giga-tronics power meters. This appendix is divided into the following major sections:

- Power Sensor Selection
- Power Sensor Calibration

B.2 Power Sensor Selection

Standard Series 803XXA Sensors measure CW signals from -70 to +20 dBm; and the Series 804XXA Sensors measure modulated or CW signals from -67 to +20 dBm; the 58542 VXIbus Universal Power Meter also use Peak Power Sensors for measuring radar and digital modulation signals.

Giga-tronics True RMS sensors are recommended for applications such as measuring quadrature modulated signals, multi-tone receiver intermodulation distortion power, noise power, or the compression power of an amplifier. These sensors include a pad to attenuate the signal to the RMS region of the diode's response. This corresponds to the -70 dBm to -20 dBm linear operating region of Standard CW Sensors. The pad improves the input VSWR to ≤ 1.15 at 18 GHz.

High Power (1, 5, 25 and 50 Watt) and Low VSWR sensors are also available for use with the power meter.

Table B-1 lists the Giga-tronics power sensors used with the power meters. Refer to applicable notes on page B-4. See Figures B-1 for modulation-induced measurement uncertainty.

B.2.1 Modulation Power Sensors

Table B-1: Power Sensor Selection Guide

Model	Freq. Range/ Power Range	Max. Power	Power Linearity ⁴ (Freq > 8 GHz)	RF Conn.	Length	Dia.	Wgt.	VSWR
Standard CW Sensors								
80301A	10 MHz to 18 GHz -70 to +20 dBm	+23 dBm (200 mW)	-70 to -20 dBm ±0.00 dB -20 to +20 dBm ±0.05 dB/10 dB	Type N(m) 50Ω	114.5 mm (4.5 in)	32 mm (1.25 in)	0.18 kg (0.4 lb)	1.12:0.01 - 2 GHz 1.22:2 - 12.4 GHz 1.29:12.4 - 18 GHz
80302A				APC-7 50Ω				
80303A	10 MHz to 26.5 GHz -70 to +20 dBm		-70 to +20 dBm ±0.00 dB -20 to +20 dBm ±0.1 dB/10 dB	Type K(m) ¹ 50Ω				
80304A	10 MHz to 40 GHz -70 to 0 dBm	-70 to -20 dBm ±0.00 dB -20 to 0 dBm ±0.2 dB/10 dB						
Low VSWR CW Sensors								
80310A	10 MHz to 18 GHz -64 to +26 dBm	+29 dBm (800 mW)	-64 to -14 dBm ±0.00 dB -14 to +26 dBm ±0.05 dB/10 dB	Type K(m) ¹ 50W	127mm (5.0 in)	32 mm (1.25 in)	0.23 kg (0.5lb)	1.13:0.01 - 2 GHz 1.15:2 - 12 GHz 1.23:12 - 18 GHz 1.29:18 - 26.5 GHz 1.50:26.5 - 40 GHz
80313A	10 MHz to 26.5 GHz -64 to +26 dBm		-64 to -14 dBm ±0.00 dB -14 to +26 dBm ±0.1 dB/10 dB					
80314A	10 MHz to 40 GHz -64 to +6 dBm		-64 to -14 dBm ±0.00 dB -14 to +6 dBm ±0.2 dB/10 dB					
1W CW Sensors								
80320A	10 MHz to 18 GHz -60 to +30 dBm	+30 dBm (1 W)	-60 to -10 dBm ±0.00 dB -10 to +30 dBm ±0.05 dB/10 dB	Type K(m) ¹ 50Ω	127 mm (5.0 in)	32 mm (1.25 in)	0.23 kg (0.5 lb)	1.11:0.01 - 2 GHz 1.12:2 - 12 GHz 1.18:12 - 18 GHz 1.22:18 - 26.5 GHz 1.36:26.5 - 40 GHz
80323A	10 MHz to 26.5 GHz -60 to +30 dBm		-60 to -10 dBm ±0.00 dB -10 to +30 dBm ±0.1 dB/10 dB					
80324A	10 MHz to 40 GHz -60 to +10 dBm		-60 to -10 dBm ±0.00 dB -10 to +10 dBm ±0.2 dB/10 dB					

Table B-1: Power Sensor Selection Guide (Continued)

Model	Freq. Range/ Power Range	Max. Power	Power Linearity ⁴ (Freq > 8 GHz)	RF Conn.	Length	Dia.	Wgt.	VSWR
5W CW Sensor²								
80321A	10 MHz to 18 GHz -50 to +37 dBm	+37 dBm (5 W)	-50 to +0 dBm ± 0.00 dB 0 to +37 dBm ± 0.05 dB/10 dB	Type N(m) 50 Ω	150 mm (5.9 in)	32 mm (1.25 in)	0.23 kg (0.5 lb)	1.20:0.01 - 2 GHz 1.25:6 - 12.4 GHz 1.35:12.4 - 18 GHz
25W CW Sensor³								
80322A	10 MHz to 18 GHz -40 to +44 dBm	+44 dBm (25 W)	-40 to +10 dBm ± 0.00 dB +10 to +44 dBm ± 0.05 dB/10 dB	Type N(m) 50 Ω	230 mm (9.0 in)	104 mm (4.1 in)	0.3 kg (0.6 lb)	1.20:0.01 - 2 GHz 1.30:6 - 12.4 GHz 1.40:12.4 - 18 GHz
50W CW Sensor³								
80325A	10 MHz to 18 GHz -40 to +47 dBm	+47 dBm (50 W)	-40 to +10 dBm ± 0.00 dB +10 to +47 dBm ± 0.05 dB/10 dB	Type N(m) 50 Ω	230mm (9.0 in)	104 mm (4.1 in)	0.3 kg (0.6 lb)	1.25:0.01 - 2 GHz 1.35:6 - 12.4 GHz 1.45:12.4 - 18 GHz
True RMS Sensors (-30 to +20 dBm)								
80330A 80333A 80334A	10 MHz to 18 GHz 10 MHz to 26.5 GHz 10 MHz to 40 GHz	+33 dBm (2 W)	-30 to +20 dBm ± 0.00 dB	Type K(m) ¹ 50 Ω	152.5 mm (6.0 in)	32 mm 1.25 in)	0.27 kg (0.6 lb)	1.12:0.01 - 12 GHz 1.15:12 - 18 GHz 1.18:18 - 26.5 GHz 1.29:26.5 - 40 GHz
80340 Series Peak Power Sensors (-30 to +20 dBm)								
80340A	50 MHz to 18 GHz	+23 dBm (200 mW)	-30 to -20 dBm ± 0.13 dB 0 to +20 dBm	Type N(m) ¹ 50 Ω	146 mm (5.75 in)	37 mm (1.44 in)	0.3 kg (0.6lb)	1.12:0.01 - 2 GHz 1.22:2 - 12.4 GHz 1.37:12.4 - 18 GHz
80343A 80344A	50 MHz to 26.5 GHz 50 MHz to 40 GHz		± 0.13 dB ± 0.01 dB/dB	Type K(m) ¹ 50 Ω				1.50:18 - 26.5 GHz 1.92:26.5 - 40 GHz

Notes:

1. The K connector is electrically and mechanically compatible with the APC-3.5 and SMA connectors.
2. Power coefficient equals <0.01 dB/Watt.
3. Power coefficient equals <0.015 dB/Watt.
4. For frequencies above 8 GHz, add power linearity to system linearity.
5. Peak operating range above CW maximum range is limited to <10% duty cycle.
6. Includes uncertainty of reference standard and transfer uncertainty. Directly traceable to NIST.
7. Square root of sum of the individual uncertainties squared (RSS).
8. Cal Factor numbers allow for 3% repeatability when connecting attenuator to sensor, and 3% for attenuator measurement uncertainty and mismatch of sensor/pad combination. Attenuator frequency response is added to the Sensor Cal Factors which are stored in the sensor's EEPROM.

Table B-2: Power Sensor Cal Factor Uncertainties

Freq. (GHz)		Sum of Uncertainties (%) ⁶						Probable Uncertainties (%) ⁷					
Lower	Upper	80301A 80302A 80340 80401A 80402 80303 80304 80343 80344	80310A 80313A 80314A	80320A 80323A 80324A	80321A ⁸ 80322A ⁸ 80325A ⁸	80330A 80333A 80334A	80301 80302 80340 80401A 80402 80303 80304 80343 80344	80310A 80313A 80314A	80320A 80323A 80324A	80321A ⁸ 80322A ⁸ 80325A ⁸	80330A 80333A 80334A	80321A ⁸ 80322A ⁸ 80325A ⁸	80330A ⁸ 80333A ⁸ 80334A ⁸
0.1	1	1.61	3.06	2.98	2.96	7.61	2.95	1.04	1.64	1.58	1.58	4.54	1.58
1	2	1.95	3.51	3.58	3.57	7.95	3.55	1.20	1.73	1.73	1.73	4.67	1.73
2	4	2.44	4.42	4.33	4.29	8.44	4.27	1.33	1.93	1.91	1.91	4.89	1.90
4	6	2.67	4.74	4.67	4.63	8.67	4.60	1.41	2.03	2.02	2.01	5.01	2.01
6	8	2.86	4.94	4.87	4.82	8.86	4.80	1.52	2.08	2.07	2.06	5.12	2.06
8	12.4	3.59	6.04	5.95	5.90	9.59	5.87	1.92	2.55	2.54	2.53	5.56	2.53
12.4	18	4.09	6.86	6.76	6.69	10.09	6.64	2.11	2.83	2.80	2.79	5.89	2.78
18	26.5	---	9.27	9.43	9.28	---	9.21	---	3.63	3.68	3.62	---	3.59
26.5	40	---	15.19	14.20	13.86	---	13.66	---	6.05	5.54	5.39	---	5.30

Notes:

1. The K connector is electrically and mechanically compatible with the APC-3.5 and SMA connectors.
2. Power coefficient equals <0.01 dB/Watt.
3. Power coefficient equals <0.015 dB/Watt.
4. For frequencies above 8 GHz, add power linearity to system linearity.
5. Peak operating range above CW maximum range is limited to <10% duty cycle.
6. Includes uncertainty of reference standard and transfer uncertainty. Directly traceable to NIST.
7. Square root of sum of the individual uncertainties squared (RSS).
8. Cal Factor numbers allow for 3% repeatability when connecting attenuator to sensor, and 3% for attenuator measurement uncertainty and mismatch of sensor/pad combination. Attenuator frequency response is added to the Sensor Cal Factors which are stored in the sensor's EEPROM.

Modulation-Induced Measurement Uncertainty for the 80401A Sensor




Figure B-1: 80401A Modulation-Related Uncertainty

B.2.2 BAP Mode Limitations

The minimum input level is -40 dBm (average); the minimum pulse repetition frequency is 20 Hz. If the input signal does not meet these minima, **BURST AVG** LED will flash to indicate that the input is not suitable for BAP measurement. The power meter will continue to read the input but the BAP measurement algorithms will not be able to synchronize to the modulation of the input; the input will

58542 VXIbus Universal Power Meter

be measured as if the power meter were in MAP mode. In addition, some measurement inaccuracy will result if the instantaneous power within the pulse falls below -43 dBm; however, this condition will not cause LED to flash.

B.2.3 Peak Power Sensors

Table B-3: 8035XA Peak Power Sensor Selection Guide

Peak Power Sensors								
Model	Freq. Range/ Power Range	Max. Power	Power Linearity ⁴	RF Conn.	Dimensions		Wgt.	VSWR
					Length	Dia.		
Standard Peak Power Sensors								
80350A	45 MHz to 18 GHz -20 to +20 dBm, Peak -30 to +20 dBm, CW	+ 23 dBm (200 mW) CW or Peak	-30 to -20 dBm ±0.00 dB -20 to +20 dBm ±0.05 dB/10 dB	Type N(m) 50Ω	165 mm (6.5 in)	37 mm 1.25 in)	0.3 kg (0.7 lb)	1.12:0.045 - 2 GHz 1.22:2 - 12.4 GHz 1.37:12.4 - 18 GHz
80353A	45 MHz to 26.5 GHz -20 to +20 dBm, Peak -30 to +20 dBm, CW		-30 to -20 dBm ±0.00 dB -20 to +20 dBm ±0.1 dB/10 dB	Type K(m) ¹ 50Ω				1.12:0.045 - 2 GHz 1.22:2 - 12.4 GHz 1.37:12.4 - 18 GHz 1.50:18 - 26.5 GHz
80354A	45 MHz to 40 GHz -20 to +0.0 dBm, Peak -30 to +0.0 dBm, CW		-30 to -20 dBm ±0.00 dB -20 to 0.0 dBm ±0.2 dB/10dB					1.12:0.045 - 2 GHz 1.22:2 - 12.4 GHz 1.37:12.4 - 18 GHz 1.50:18 - 26.5 GHz 1.92:26.5 - 40 GHz
5W Peak Power Sensor ^{2,5}								
80351A	45 MHz to 18 GHz 0.0 to +40 dBm, Peak -10 to +37 dBm, CW	CW: +37 dBm (5 W Avg.) Peak: +43 dBm	-10 to +0 dBm ±0.00 dB +0 to +40 dBm ±0.05 dB/10 dB	Type N(m) 50Ω	200 mm (7.9 in)	37 mm (1.25 in)	0.3 kg (0.7 lb)	1.15:0.045 - 4 GHz 1.25:6 - 12.4 GHz 1.35:12.4 - 18 GHz
25W Peak Power Sensor ^{3,5}								
80352A	45 MHz to 18 GHz +10 to +50 dBm, Peak 0.0 to +44 dBm, CW	CW: +44 dBm (25 W Avg.) Peak: +53 dBm	0.0 to +10 dBm ±0.00 dB +10 to +50 dBm ±0.05 dB/10 dB	Type N(m) 50Ω	280 mm (11.0 in)	104 mm (4.1 in)	0.3 kg (0.7 lb)	1.20:0.045 - 6 GHz 1.30:6 - 12.4 GHz 1.40:12.4 - 18 GHz
50W Peak Power Sensor ^{3,5}								
80355A	45 MHz to 18 GHz +10 to +50 dBm, Peak 0.0 to +47 dBm, CW	CW: +47 dBm (50 W Avg.) Peak: +53 dBm	0.0 to +10 dBm ±0.00 dB +10 to +50 dBm ±0.05 dB/10 dB	Type N(m) 50Ω	280 mm (11.0 in)	104 mm (4.1 in)	0.3 kg (0.7 lb)	1.25:0.045 - 6 GHz 1.35:6 - 12.4 GHz 1.45:12.4 - 18 GHz

Notes:

1. The K connector is electrically and mechanically compatible with the APC-3.5 and SMA connectors.
2. Power coefficient equals <0.01 dB/Watt (AVG).
3. Power coefficient equals <0.015 dB/Watt (AVG).
4. For frequencies above 8 GHz, add power linearity to system linearity.
5. Peak operating range above CW maximum range is limited to <10% duty cycle.

Table B-4: Peak Power Sensor Cal Factor Uncertainties

Freq. (GHz)		Sum of Uncertainties (%) ¹					Probable Uncertainties (%) ²		
Lower	Upper	80350A	80353A 80354A	80351A ³	80352A ³	80355A ³	80350A	80353A 80354A	80351A ³ 80352A ³ 80355A ³
0.1	1	1.61	3.06	9.09	9.51	10.16	1.04	1.64	4.92
1	2	1.95	3.51	9.43	9.85	10.50	1.20	1.73	5.04
2	4	2.44	4.42	13.10	13.57	14.52	1.33	1.93	7.09
4	6	2.67	4.74	13.33	13.80	14.75	1.41	2.03	7.17
6	8	2.86	4.94	13.52	13.99	14.94	1.52	2.08	7.25
8	12.4	3.59	6.04	14.25	14.72	15.67	1.92	2.55	7.56
12.4	18	4.09	6.86	19.52	20.97	21.94	2.11	2.83	12.37
18	26.5	---	9.27	---	---	---	---	3.63	---
26.5	40	---	15.19	---	---	---	---	6.05	---

Notes:

1. Includes uncertainty of reference standard and transfer uncertainty. Directly traceable to NIST.
2. Square root of sum of the individual uncertainties squared (RSS).
3. Cal Factor numbers allow for 3% repeatability when connecting attenuator to sensor, and 3% for attenuator measurement uncertainty and mismatch of sensor/pad combination. Attenuator frequency response is added to the Sensor Cal Factors which are stored in the sensor's EEPROM.

For additional specifications, see the Series 80350A (P/N 21568) publication and data sheet.

B.2.4 Directional Bridges

The 80500 CW Directional Bridges are designed specifically for use with Giga-tronics power meters to measure the Return Loss/SWR of a test device. Each bridge includes an EEPROM which has been programmed with Identification Data for that bridge.

Table B-5: Directional Bridge Selection Guide

Precision CW Return Loss Bridges								
Model	Freq. Range/ Power Range	Max. Power	Power Linearity ⁴ (Frequency > ⁸ GHz)	Input	Test Port	Directivity	Wgt.	VSWR
80501	10 MHz to 18 GHz -35 to +20 dBm	+27 dBm (0.5W)	-35 to +10 dBm ±0.1 dB +10 to +20 dBm ±0.1 dB ±0.005 dB/dB	Type N(f) 50 Ω	Type N(f) 50 Ω	38 dB	0.340 kg	< 1.17:0.01 - 8 GHz < 1.27:8 - 18 GHz
80502	10 MHz to 18 GHz -35 to +20 dBm	+27 dBm (0.5 W)	-35 to +10 dBm ±0.1 dB +10 to +20 dBm ±0.1 dB ±0.005 dB/dB	Type N(f) 50 Ω	APC-7(f) 50 Ω	40 dB	0.340 kg	< 1.13:0.01 - 8 GHz < 1.22:8 - 18 GHz
80503	10 MHz to 26.5 GHz -35 to +20 dBm	+27 dBm (0.5 W)	-35 to +10 dBm ±0.1 dB +10 to +20 dBm ±0.1 dB ±0.005 dB/dB	SMA(f) 50 Ω	SMA(f) 50 Ω	35 dB	0.340 kg	< 1.22:0.01 - 18 GHz < 1.27:8 - 26.5 GHz
80504	10 MHz to 40 GHz -35 to +20 dBm	+27 dBm (0.5 W)	-35 to +10 dBm ±0.1 dB +10 to +20 dBm ±0.1 dB ±0.005 dB/dB	Type K(f) 50 Ω	Type K(f) 50 Ω	30 dB	0.198 kg	< 1.35:0.01 - 26.5 GHz < 1.44:26.5 - 40 GHz

The Selection Guide in Table B-5 shows primary specifications. Additional specifications are:

Bridge Frequency Response

Return loss measurements using the 8541/8542 power meter can be frequency compensated using the standard *Open/Short* supplied with the bridge.

Insertion Loss


6.5 dB, nominal, from input port to test port

Maximum Input Power

+27 dBm (0.5 W)

Directional Bridge Linearity Plus Zero Set & Noise vs. Input Power (50 MHz, 25 °C ±5 °C)

See Table below



Dimensions

80501	76 x 50 x 28 mm (3 x 2 x 1-1/8 in.)
80502	76 x 50 x 28 mm (3 x 2 x 1-1/8 in.)
80503	19 x 38 x 29 mm (3/4 x 1-1/2 x 2-1/8 in.)
80504	19 x 38 x 29 mm (3/4 x 1-1/2 x 2-1/8 in.)

Weight

80501	340 g (12 oz.)
80502	340 g (12 oz.)
80503	198 (7 oz.)
80504	198 (7 oz.)

Directional Bridge Accessories

An Open/Short is included for establishing the 0 dB return loss reference during path calibration.

B.3 Power Sensor Calibration

This procedure is for calibrating a power sensor by remote control with a 58542 VXIbus Universal Power Meter over the IEEE 488 interface bus. This procedure writes the cal factors to the sensor EEPROM.

Power sensors have built-in EEPROM data that manage the cal factors by a set of frequencies entered during calibration of the sensor at the factory. The user can program additional cal factors with special data for user-specific frequencies. A cal factor expressed in dB is programmed for each factory-calibrated frequency. The calibration process compares the measurement to the frequency standard and applies the cal factor to offset frequency deviations.

B.3.1 Equipment Required

58542 VXIbus Universal Power Meter • GPIB Controller • Power Sensor




Figure B-1: Power Sensor Calibration Setup

B.3.2 Procedure

Connect the power sensor to Channel 1 or 2 on the 58542 front panel and perform the following steps. In this procedure, bold letters are commands; the query form of a command has a question mark (?) at the end of the command. This form returns the data in the EEPROM.

1. **DIAG:SENS1 (or 2):EEPROM:READ**

Read sensor 1 (or 2) EEPROM data into the 58542 editor buffer.

Example: OUTPUT@ PWR_MTR; **DIAG:SENS1:EEPROM:READ**

2. (Optional) **DIAG:SENS < 1 OR 2 > :EEPROM:CALFR?**
 - a.) Query sensor 1 (or 2) standard cal factor start frequency, number of standard frequencies and number of special frequencies.
 - b.) Read the standard cal from the input buffer and extract the start frequency and number of standard frequencies.
 - c.) Calculate and set the frequencies of the cal factor table.
3. **DIAG:SENS < 1 or 2 > :EEPROM:CALFST?**
 - a.) Query sensor 1 (or 2) standard cal factor table.
 - b.) Read the standard cal from the input buffer and extract the standard cal factor; e.g., INPUT (GPIB address).
 - c.) DIAG:SENS<1 OR 2>:EEPROM:CALFST^{space}0.02, 0.03,0.04,0.05,0.06,0.07,0.08,0.09,0.10,0.11,0.12,0.13,0.14,0.15,0.16,0.17,0.18" form to write to editor buffer.
 - d.) Set the sensor standard cal factor table.
 - e.) Make changes from the table and put them back into the table.
 - f.) After all changes are made, put the table back into the input buffer.
4. **DIAG:SENS < 1 or 2 > :EEPROM:WRITE 0**
 - a.) Write sensor 1 (or 2) EEPROM data into the 58542 buffer. If no password has been set up, use 0 for a password.
 - b.) Restore the input buffer from step 3.d above to the EEPROM buffer (e.g., OUTPUT [GPIB] address, input buffer).
 - c.) Write sensor 1 (or 2) editor buffer data into the EEPROM with the password number, e.g., OUTPUT (GPIB address, DIAG:SENS1 (OR 2):EEPROM:WRITE 0).
 - d.) Editing the EEPROM routine is complete.

Sensor EEPROM Code Sequence Writing:

(The following program example is written in Microsoft® Visual Basic using National Instruments® VISA Instrument calls)

```
Private Sub cmdWriteNewData_Click()  
    'Write new calibration data to sensor for form  
  
    cmdWriteNewData.Caption = "Writing"  
  
    wrt = "DIAG:SENS" + SensNum + ":EEPROM:TYPE " + space$(1) _  
        + Chr$(34) + txtModelNum.Text + "," + txtSerNum.Text + "," + _  
        txtCalLoc.Text + "," + MinVal + "," + HourVal + "," + DayVal + _  
        "," + MonthVal + "," + YearVal + "," + PWDVal + Chr$(34)  
  
    stat = viWrite(MVISAAddress, wrt, Len(wrt), retCnt)  
  
    SensorWrite 'Call Write new type data  
  
    wrt = "DIAG:SENS" + SensNum + ":EEPROM:CALFR" + space$(1) + _  
        Chr$(34) + "2.000e9,1.000e9,17,1" + Chr$(34) + txtCalFreq.Text  
  
    stat = viWrite(MVISAAddress, wrt, Len(wrt), retCnt)  
  
    SensorWrite 'Call Write new range data  
  
    wrt = "DIAG:SENS" + SensNum + ":EEPROM:CALFST" + space$(1) _  
        + Chr$(34) + Str(txtCF1) + "," + Str(txtCF2) + "," + _  
        + Str(txtCF3) + "," + Str(txtCF4) + "," + Str(txtCF5) + _  
        + Str(txtCF6) + "," + Str(txtCF7) + "," + Str(txtCF8) + _  
        + Str(txtCF9) + "," + Str(txtCF10) + "," + _  
        + Str(txtCF11) + "," + Str(txtCF12) + "," + Str(txtCF13) + _  
        + Str(txtCF14) + "," + Str(txtCF15) + "," + Str(txtCF16) + _  
        + Str(txtCF17) + Chr$(34)  
  
    stat = viWrite(MVISAAddress, wrt, Len(wrt), retCnt)  
  
    SensorWrite 'Call Write new cal factor data  
  
    stat = viClear(MVISAAddress)  
    rd = ""  
    Beep  
  
    cmdWriteNewData.Caption = "Write New Information"  
End Sub  
  
Public Sub SensorWrite()  
    wrt = "DIAG:SENS" + SensNum + ":EEPROM:WRIT 0"  
  
    stat = viWrite(MVISAAddress, wrt, Len(wrt), retCnt)  
  
    Sleep (5000) 'Wait five seconds  
  
End Sub
```



Options

C.1 Introduction

This appendix describes all options that are currently available for use with the 58542 VXIbus Universal Power Meter.

C.2 Option 02: 256K Buffer

Option 02 (P/N 21335) adds 256K Buffer for Burst Mode readings. The following parts will be installed at the factory when the 58542 is ordered with this option.

21335		EXTRA MEMORY, 128K, 8540/02, REV. A				
Item		P/N	Qty	Cage	Mfr's P/N	Description
U	29	21165	1	61802	TC551001BPL-85	TC551001BPL-10 1M RAM
U	30	21165	1	61802	TC551001BPL-85	TC551001BPL-10 1M RAM

58542 VXIbus Universal Power Meter

Numerics

50 MHz Oscillator 3-5

A

About this Publication ix

Analog

Output (Commands) 2-46

PC Board (A1) 3-2

Approximate Measuring Speeds 2-32

Arming the Triggering Cycle 2-24

Averaging 2-36

B

BAP Mode Limitations B-7

Bus Error Timer 3-11

C

Cal Factor

Correction 2-27

Error Control 2-29

Examples A-29

Calculate Subsystem Commands 2-8

Calibration

Equipment Required 4-1

Procedures 4-2

Sensor Calibration & Zeroing 2-5, 2-17

Calibrator

Controls 2-53

Frequency Check 4-7

Module 3-4

NVRAM Control Circuit 3-7

Output Power 4-5

Output Power Reference Level 4-2

Voltages 4-7

Channel

Configuration 2-25

Difference Measurement A-28

Examples A-28

Ratio Measurement A-28

Single Sensor Power Measurement A-28

Troubleshooting (58542 - Channel 2) 5-4

Circuit Description 3-1

Command Interface

GPIB Command Syntax 2-12

Commands in Brackets 2-12

Conventions (Publication) xi

Cooling 1-2

Correction Thermistor Circuit 3-7

CPU & Memory 3-11

Bus Error Timer 3-11

Drivers & Transceivers 3-11

Interrupt Controller 3-11

LED Drivers 3-11

Local Address Decoders 3-11

Local Memory 3-11

Processor 3-11

Real Time Clock/Timer 3-11

D

Data Transfer Bus Arbitration 2-3

Description (58542) 1-1

Diagnostic

Commands 2-7

Test Commands 5-5

Difference Measurement A-28

Digital

Control Circuit 3-7

PC Board (A2) 3-8

Directional Bridges B-10

Drivers & Transceivers 3-10, 3-11

E

Equipment Required (Calibration & Testing) 4-1

Error

Control 2-37

Messages 2-59

Special 2-20

Event Status Register 2-41

G

GPIB

Command Syntax

Commands in Brackets 2-12

Italics in Syntax Descriptions 2-12

Link Command Strings 2-12

Measurement Data Output Format 2-12

Programmer Selective Parameters 2-12

Query Format 2-12

Port Check 4-8

Test Functions 5-4

H

- Halting Operation 2-49
- High Speed Measurement 2-30, A-35
 - Measurement Level Notes 2-33
 - Measurement Speeds 2-33
 - Operating Mode Control 2-30
 - Triggering Notes 2-33

I

- Identification
 - Instrument A-48
 - Sensor Model A-49
 - Sensor Serial Number A-51
- Identification Commands 2-52
- IEEE 488.2 Required Commands 2-7
- Initial Setup 2-2
 - Address (Logical) 2-2
- Installation 2-1
- Instrument
 - Triggering 2-21
- Instrument & Sensor Identification A-48
- Interrupt Controller 3-11
- Introduction
 - Calibration & Testing 4-1
 - Diagrams 7-1
 - Maintenance 5-1
 - Options C-1
 - Parts Lists 6-1
 - Power Sensors B-1
 - Program Examples A-1
 - Theory of Operation 3-1
- Italics in Syntax Descriptions 2-12
- Items
 - Furnished 1-2
 - Required 1-2

L

- LED Drivers 3-11
- Limit Line Configuration & Monitoring 2-44
- Linking Command Strings 2-12
- List of Manufacturers 6-31
- Lithium Battery 5-2
- Local
 - Address Decoders 3-11
 - Memory 3-11
- Logical
 - Address 2-2
 - Address Switch 3-10

M

- Maintenance
 - Channel 2 Troubleshooting 5-4
 - Diagnostic Test Commands 5-5
 - GPIO Test Functions 5-4
 - Lithium Battery 5-2
 - Replacement Procedure 5-2
 - Power Supply Voltage Checks 5-1
- Measurement
 - Collection
 - Modes
 - Averaging 2-36
 - Standard
 - Triggering 2-6
 - Data Output Format 2-12
 - Level Notes 2-33
 - Speeds 2-33
 - Triggering 2-6
- Memory Functions 2-6
- Min/Max Configuration & Monitoring 2-43
- Modulation
 - Power Sensors B-2
 - Sensor Specifications B-6

O

- Offsets 2-38
- Operating Mode Control 2-30
- Operation 2-5
 - Power Sensors B-1
- Option 02
 - 256K Buffer C-1
- Oven 3-6

P

- Parts Lists (58542) 6-1
- Peak Power
 - Sensor Triggering 2-34
 - Sensors B-8
- Performance Verification 4-8
- Power
 - Supply Voltage Checks 5-1
- Power Sensors B-1
 - BAP Mode Limitations B-7
 - Calibration B-12
 - Directional Bridges B-10
 - Introduction B-1
 - Linearity 4-10
 - Modulation Sensor Specifications B-6
 - Peak B-8
 - Peak Power Sensor Triggering 2-34
 - Selection B-1
 - Specifications B-1
- Preparation for Use 2-1
- Preset Configuration 2-50
- Processor 3-11

Program Examples
 Cal Factor A-29
 Channel Configuration A-28
 Error Control A-8
 High Speed Measurement A-35
 Instrument & Sensor Identification A-48
 Instrument Triggering A-22
 Reading Power Measurement A-12
 Relative or Referenced Measurement A-43
 Sensor Calibration A-1
 Sensor Zeroing A-7
 SRQ Interrupt A-46
 Programmer Selective Parameters 2-12

Q

Query Format 2-12

R

Ratio Measurement A-28
 Reading Power Measurement 2-19
 Real Time Clock/Timer 3-11
 Receiving Inspection 1-2
 Record of Publication Changes xiii
 Relative or Referenced Measurement 2-37, A-43
 Remote Operation
 Power Sensors B-1
 SCPI Command Interface 2-5
 Reshipment Preparation 1-3
 RF Output 3-5

S

Safety Precautions 1-3
 Saving & Recalling Configurations 2-49
 SCPI Command Interface 2-5
 Arming the Triggering Cycle 2-24
 Averaging 2-36
 Cal Factor Correction 2-27
 Calculate Subsystem Commands 2-8
 Calibrator Controls 2-53
 Channel Configuration 2-6, 2-25
 Error Messages 2-59
 GPIB Command Syntax 2-12
 Halting Operation 2-49
 High Speed Measurements 2-30
 Identification Commands 2-52
 IEEE 488.2 Required Commands 2-7
 Instrument Triggering 2-21
 Limit Line Configuration & Monitoring 2-44
 Measurement Triggering 2-6
 Memory Functions 2-6
 Min/Max Configuration & Monitoring 2-43
 Offsets 2-38
 Peak Power Sensor Triggering 2-34
 Preset Configuration 2-50
 Reading Power Measurements 2-19
 Referenced Measurement 2-37

Relative Measurement 2-37
 Self-Test 2-55
 Sense Subsystem Commands 2-9
 Sensor & Channel Configuration 2-6, 2-25
 Sensor Calibration & Zeroing 2-5, 2-17
 Sensor EEPROM Commands 2-53
 SRQ & Status Monitoring 2-39
 Trigger Subsystem Commands 2-11
 Self-Test 2-55
 Sense Subsystem Commands 2-9
 Sensor
 Calibration 2-17
 Calibration & Zeroing 2-5, 2-17
 Calibration Examples A-1
 EEPROM Commands 2-53
 Error Control Examples A-8
 Interrupt 3-7
 Model Identification A-49
 NVRAM 3-7
 Precautions 2-4
 Sensor & Channel Configuration 2-6
 Serial Number Identification A-51
 Single Sensor Power Measurement A-28
 Zero 2-18
 Zeroing Examples A-7
 Shared Memory 3-10
 Decoders 3-10
 Special Configurations xv
 Specifications 1-4
 Accuracy 1-4
 Inputs/Outputs 1-8
 Measurement Speed 1-7
 Meter Functions 1-7
 Power Requirements 1-8
 Range 1-4
 Zeroing Accuracy (Std. CW Sensors) 1-5
 SRQ
 Interrupt
 Examples A-46
 SRQ & Status Monitoring 2-39
 Event Status Register 2-41
 Status
 Event Status Register 2-41
 Status Byte Register 2-42
 Storage 1-2
 Store & Recall 2-49

T

Theory of Operation 3-1
 Analog PC Board (A1) 3-2
 Calibrator Module 3-4
 Circuit Description 3-1
 Digital PC Board (A2) 3-8
 VXI Processor PC Board (A3) 3-9
 Thermistor Bridge 3-6
 Tools & Equipment 1-2
 Track & Hold and DAC 3-6
 Trigger Subsystem Commands 2-11
 Triggering
 Arming the Triggering Cycle 2-24
 Instrument Triggering 2-21
 Notes 2-33
 Peak Power Sensor Triggering 2-34
 TTL Triggers & Local Bus 3-10

58542 VXIbus Universal Power Meter

V

V_{PROP}F Configuration 2-29

VXI

- Drivers & Transceivers 3-10
- Gate Array 3-9
- Interface 3-9
- Logical Address Switch 3-10
- Processor PC Board (A3) 3-9
- Shared Memory Decoders 3-10
- Shared Memroy 3-10
- TTL Triggers & Local Bus 3-10

Z

Zeroing

- Sensor Calibration & Zeroing 2-5, 2-17