

HP 35639A Data Viewer

Do You Ever Need To ...

- Examine measurement results on a PC?
- Incorporate measurement data into a written report?
- Annotate displays to mark areas of interest?
- Pick data peaks - automatically?
- Send measurement data to a PC spreadsheet program?
- Print lots of measurement data -automatically?
- Print graphical measurement results in a prescribed format?


The HP 35639A can solve these problems - and more

What is the HP 35639A Data Viewer?





- Microsoft Windows software application
- Works from saved measurement files (SDF, VEE, ASCII, and others)
- Provides versatile data viewing on a PC
- Provides seamless integration of data with Windows word processors, spreadsheets, and other applications
- Software, manuals, and on-line Help text
- \$710 US List

Windows-based User Interface






Data Examination on a PC




- Compare data from different instruments - without the instruments
- Markers - absolute, relative, peak
- Display functions - mag, phase, dB, logmag, polar, real, imag, Nyquist, eye
- Display types - single, overlaid, map
- Units - peak/RMS, EU's
- Auto-scaling display
- Saved measurement results on a LAN are available to anyone, anywhere who has the HP 35639A
- Measurement data is never obsolete

Choose the Display That's Best for Your Data




Report Generation Using Cut and Paste



- Paste graphics into Windows word processors
- Change fonts, colors, line widths, grid styles
- Paste graphics into graphics editors for even more complete customization
- Save customized display formats as "templates," then re-use them later
- Paste data into spreadsheets and application software
- This presentation was created with the HP 35639A

Create Custom Prints Automatically



- Layout pages with multiple displays per page
- Use annotation and arrows to add information
- Create custom page templates for re-use
- Batch plot data using templates
- Create page layouts that conform to existing standards

Convert Data to Other File Formats

Import Data Formats

- SDF Data
- SDF Time Capture
- VEE (time and spectrum)
- ASCII Text and CSV
- 3562/63A

Export Data Formats

- SDF Data
- SDF Time Capture
- ASCII Text and CSV
- MATLAB
- 3562/63A

Instruments that Create SDF Files

- 3560A
- 3562/63A
- 3566/67A
- 35665A
- 35670A
- 3569A
- 3587S
- 3588/89A
- 89410A
- 89440A
- 89441A

HP 35639A Positioning and Sales Tools

- Use the HP 35639A as a competitive edge - no one else has it
 - "The HP 35639A makes your instruments work harder."
 - "Your data will never be obsolete if it's SDF."
 - "Share data between instruments - view data from all instruments."
 - "You shouldn't need an instrument just to use the data."
 - "Get the data where you want it most - on your PC."
- Target customers - the installed base, plus new sales
- HP 35639A Product Overview PN 5962-9499E
- Customer presentation slides (on LSIDBB)
- Price - \$709 US list
- Shipping now