



U.S. Department
of Transportation
Federal Aviation
Administration

Small Airplane Directorate
Atlanta Aircraft Certification Office
One Crown Center, Suite 450
1895 Phoenix Boulevard
Atlanta, GA 30349

MAY 03 2004

Ms. Mary Gayle Wright
Sr. Business Development Manager,
Commercial Products
L-3 Communications, Display Systems
1355 Bluegrass Lakes Parkway
Alpharetta, GA 30004

Dear Ms. Wright

This letter supplements our original letters of authorization to identify a software version change to the following Pilot Vehicle Interface (PVI) Series 600 Multi-function display (MFD) Part Number and the PVI Series 600 MFD Terrain Awareness Warning (TAWS) Part Number listed below:

Part Number:	V63A010-00-001
Description:	PVI MFD
Part number:	V63A010-00-001-001
Description:	PVI MFD TAWS
TSO Marking:	C105, C113
Software Version:	OFP V631016-01-000, Version 1.3

Effective this date you are authorized to identify the changes with the appropriate Technical Standard Order (TSO) marking required by 14 CFR, Part 21.607(d) and shown on Software Configuration Index Document No. V63A015-14-002, Revision A, and V63A015-14-001, Revision C, both dated April 8, 2004.

This office accepts your statement of compliance with RTCA DO-178B, Level B category requirements. This compliance finding should not be considered an installation approval and the installation may be subject to additional software review relating to the

integration of this equipment into an airframe. Verification of compatibility with a particular aircraft installation is the responsibility of the installer and may require further FAA analysis, possible flight test and changes to a Flight Manual Supplement.

Sincerely,



Eugene L. Bollin
Associate Manager,
Atlanta Aircraft Certification Office