

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: September, 2006

PDB Number:05061-PDB

Product

5061A Replacement Cesium Beam Tube

Overview

Symmetricom has discontinued the Symmetricom Model 05061 series Cesium Beam Tube. The 05061 series has reached the end of its technology product lifecycle and due to economic and logistical factors the manufacturing of this product is being discontinued. Symmetricom offers direct replacements for the obsolete 05061 series that can be installed in most 5061A/B cesium frequency standards. Please contact the factory for details on replacement options.

Affected Models and Replacements

Current Model	Current Part #s	Replacement Model	Replacement Part #	Replacement Datasheet Link
Symmetricom Model 05061 series Cesium Beam Tube	05061-6077 05061-6101	Symmetricom Model 7600 series Cesium Beam Tube	74514-103 74514-504	

Contact Information

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640