



1.1 Supplier's Company Name Microsemi, Inc	1.2 Supplier's Address 3870 North 1 st Street	1.3 Supplier's City San Jose
1.4 Supplier's State CA	1.5 Supplier's Zip 95134	1.6 Supplier's Technical Contact Name CBU Tech Support
1.7 Supplier's Technical Contact Phone Number 408-428-7907	1.8 Telcordia Vendor Abbreviation TMSL	2.1 Product Change Notice Number 09761A
2.2 Product Change Notice Issue Number 1	2.3 Vendor's Change Identification Number EC09761	2.4 Supplier's Change Procedure N/A
3.0 PCN Issue Date 06/25/2014	4.1 Major System Affected TNSYNC	4.2 Subsystem Affected TimeProvider 2700 090-50201-111
4.3 Hardware Affected Y	4.4 Firmware Affected Y	4.5 Software Affected N
4.6 Plug-In Affected N/A	5.1 New Product Code 090-50201-111 Rev. F	5.2 New Firmware Code 1.1.4
6.1 Old Product Code 090-50201-111 Rev. E	6.2 Old Firmware Code 1.0.7	7.0 New CLEI Code PSMAW00BRA
8.0 Old CLEI Code PSMAK00BRA	9.0 Associated Products of Changes Affected None.	
10.1 Drawing Number N/A		10.2 Reference Drawing Number N/A
11.0 Classification of Change B	12.1 Reason for Classification Hardware changes to accommodate GNSS module obsolescence.	
12.2 Vacant		
13.0 Reason for Change 'End of Life' by our supplier of GNSS module.		
14.1 Description of Change New GNSS part introduced. No functional change in the working of the product.		
14.2 Change Verification Procedures N/A		15.1 Safety Notice N
15.2 Fire Notice N	15.3 Service Affecting N	15.4 Transmission Affecting N
15.5 Maintenance Affecting N	15.6 Reliability Affecting N	15.7 Power Affecting N
15.8 Traffic Affecting N	15.9 Describe the effect of change No effect on system performance or reliability.	
16.0 Material Affected GNSS module.		17.0 Documentation Affected N/A
18.0 Implementation Date 07/28/2014		19.0 Modification Completion Date N/A
20.1 Modification Location Sales Contacts: USA 888-367-7966 +1 +1, International +1-408-428-7907 +1 +1. Europe, Middle East & Africa +49 700 32886435		20.2 (F)ield (L)ab Trial or (N)/A N/A
21.1 Estimated Installation Time per	21.2 Modification Cost	22.0 Title of Supplier's

Product Code N/A	N/A	Location/Quantity Report N/A
23.0 Attachments None		
24.0 Comments The GNSS module hardware is backward compatible with the earlier released product firmware 1.0.7		