

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: January 1, 2007

PDB Number:PDB_4032A.Doc

Product

Symmetricom Model 4032A TTL Pulse Distribution Amplifier



Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 4032A TTL Pulse Distribution Amplifier. The 4032A has reached the end of its technology product lifecycle and is being discontinued. Symmetricom model 4033A is a drop in replacement for the 4032A.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 30, 2007

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
4032A	4032A	4033A	4033A	

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information.....

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

support@symmetricom.com

www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.

Santa Rosa, CA 95403

Telephone: 707-528-1230

Facsimile: 707-527-6640