

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: July 01, 2006

PDB Number:PDB_5401.Doc

Product

Symmetricom Model 5401 Disciplined Rubidium Oscillator



Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 5401 Disciplined Rubidium Oscillator. The 5401 has reached the end of its technology product lifecycle and is being discontinued. There is no direct replacement for this product. Similar functionality is available with other Symmetricom rubidium oscillators. See website for complete listing of available Symmetricom rubidium oscillators

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	May 1, 2007

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
5401	5401 5401-G	None None	None None	

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640