

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: May 1, 2011

PDB Number: PDB_56000 Option Modules.Doc

Product

Symmetricom Model 56000 Option Modules

Overview

Symmetricom is announcing the discontinuance of certain option modules for the 56000 Modular Time & Frequency Distribution System. These modules have reached the end of their technology product lifecycle and are being discontinued.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	August 1, 2011

Affected Part Numbers and Replacement Product Summary

Current Part #'s	Replacement Part #	Replacement Datasheet Link
560-197-12	NA	
560-5155-2	NA	
560-197-4	NA	
560-197-6	NA	
560-5141-1D	NA	
560-5195-1	NA	
560-5195-2	NA	
560-5195-3	NA	
560-5195-4	NA	
560-5208	NA	
560-5141-3i	NA	
088-23021-654	NA	
560-5181-3	NA	
560-5193	NA	
560-5194	NA	
560-5196	NA	
560-197-20	NA	

Support Policy

Repair services and technical support will be available during the warranty period. For all out-of-warranty units, service options (repair, telephone technical support, on-site maintenance, training, etc.) will be offered on a fee-basis for as long as possible and at Symmetricom's discretion. Interested

customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640