

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: June 1, 2007

PDB Number:PDB_58502A.Doc

Product

Symmetricom Model 58502A Broadband Distribution Amplifier



Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 58502A Broadband Distribution Amplifier. The 58502A has reached the end of its technology product lifecycle and is being discontinued. Symmetricom offers many alternative products with varying features that offer similar or improved performance than the 58502A.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	December 1, 2007

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement D
58502A	58502A	6502B	14364-101	http://www.symmttm.com/
		4633B	TSC-4036B	http://www.symmttm.com/
		9611A	9611	http://www.symmttm.com/
		4091A	TSC-4091A	http://www.symmttm.com/
	58502A-010	None	None	

Contact information.....

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available for 4 years after date of discontinuance. In the event of parts or component obsolescence, repairs will be made on a best effort basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services	1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA 1-408-428-7907 worldwide
-----------------------------	--

Symmetricom Customer Service:	1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA 1-408-428-7907 worldwide support@symmetricom.com www.symmetricom.com
-------------------------------	--

Timing, Test & Measurement Division:	3750 Westwind Blvd. Santa Rosa, CA 95403 Telephone: 707-528-1230 Facsimile: 707-527-6640
--------------------------------------	---