

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: January 1, 2007

PDB Number:PDB_6504B.Doc

Product

Symmetricom Model 6504B IRIGB Distribution Amplifier



Overview

Symmetricom is announcing the discontinuance of the Symmetricom Model 6504B IRIGB Distribution Amplifier. The 6504B has reached the end of its technology product lifecycle and is being discontinued. Symmetricom offers an improved and more feature rich replacement unit; model 4059B, that provides all the functionality of the 6504B along with the ability to distribute IRIG A/B or G and added features that include an Ethernet interface and 15 outputs.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	June 30, 2007

Affected Models and Replacement Product Summary

Current Model	Current Part #'s	Replacement Model	Replacement Part #	Replacement Datasheet Link
6504B	14366-101 SPCL-0007	4059B Contact Factory	4059B	

Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available on a best efforts basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information.....

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640