

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** December 4, 2007

**PDB Number:** PDB\_GPS-605.pdf

## Product

Symmetricom GPS-605 GPS Synchronized Clock and Time Code Generator



## Overview

Symmetricom is announcing the discontinuance of the GPS-605 GPS Synchronized Clock and Time Code Generator.

## Product Obsolescence Timeline

| Milestone         | Date           |
|-------------------|----------------|
| Last Day to Order | March 10, 2008 |

## Limited Availability Product Allocation

The GPS-605 is limited in availability due to a shortage of a key component. Orders during the discontinuance period will be limited to a quantity of three and may be allocated as product inventories are depleted.

## Affected Models and Replacement Product Summary

| Current Model | Current Part #s            | Replacement Model                | Replacement Part # | Replacement Datasheet Link                                                                              |
|---------------|----------------------------|----------------------------------|--------------------|---------------------------------------------------------------------------------------------------------|
| GPS-605       | 820-501-000<br>820-501-006 | XL-GPS Time & Frequency Receiver | 1530-602           | <a href="http://www.symmttm.com/pdf/Gps/DS_XL-GPS.pdf">http://www.symmttm.com/pdf/Gps/DS_XL-GPS.pdf</a> |

## Support Policy

Repair services will be available during the warranty period. For all out-of-warranty units, service options (repair, spares support, telephone technical support, on-site maintenance, training, etc.) will be available for 3 years after date of discontinuance. In the event of parts or component obsolescence, repairs will be made on a best effort basis. Interested customers should contact Symmetricom Global Services (SGS) to check a product's eligibility for services and any applicable terms.

Contact information...

**Contact Information**

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Technical Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
[support@symmetricom.com](mailto:support@symmetricom.com)  
[www.symmetricom.com](http://www.symmetricom.com)

Timing, Test & Measurement Division:

3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640