

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: June 30, 2011

PDB Number: PDB_SyncSwitch_TC100.pdf

Product

Symmetricom, SyncSwitch TC100 Transparent Clock/Managed Ethernet Switch



Discontinued: SyncSwitch TC100

Overview

Symmetricom is announcing the discontinuance of the SyncSwitch TC100 Transparent Clock/Managed Ethernet Switch. This product has reached the end of its product lifecycle.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	No longer available.
Extended Warranty Contracts (maximum expiration date)	Not applicable.
Repair End Date (Out-of-warranty repairs will not be available for this product)	July 1, 2011.
Customer Support Contracts (non-repair services)	Not applicable.

Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
SyncSwitch TC100, 10/100BaseT/TX	1550R-100	No replacement	No replacement
SyncSwitch TC100, Copper & MM Fiber	1550R-101	No replacement	No replacement
SyncSwitch TC100, Copper & SM Fiber	1550R-102	No replacement	No replacement

Contact Information

Symmetricom Global Services:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Government Business Unit:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640