

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: February 1, 2009

PDB Number: PDB_bc357VXI-C.PDF

Product

Symmetricom bc357VXI-C bus timing card.

Overview

Symmetricom is announcing the discontinuance of the VXI bus based bc357VXI-C bus timing card. This model has reached the end of its technology product lifecycle and the manufacturing of this product is being discontinued.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	July 31 st , 2009. All orders received between February 1, 2009 and July 31, 2009 may be aggregated into a single last time build of this model that will be initiated in August 2009.
Extended Warranty Contracts	Not available
Repair End Date	Best effort
Customer Support Contracts (non-repair services)	Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Customers can contact SGS for service availability and terms.

Affected Models and Alternative Product Summary

Current Model	Current Part #s	Alternative Model	Alternative Part #
bc357VXI-C	BC11963-2000	None	None

Support Policy

Product support services (telephone technical support, on-site maintenance, training, spares support, etc.) and repairs are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. All services may not be available for every product. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

Contact Information

Symmetricom Global Services

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Timing, Test & Measurement Division:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640