

PL-ELS1000(u)

Firmware Version 3.0 Release Notes

BUGS FIXED:

None.

CHANGES:

- Gas flow serial packet data now formatted to 2 decimal places

NEW FEATURES:

- New microbore (u) variant which allows programmable gas flow from 0.05 - 1.00 SLM's
- Microbore/Standard MFC identifier available via new serial command