



To ensure proper electrical and thermal performance  
there must be a ground plane with 100%  
solder connection underneath the part



Part Is Symmetric About All Axis



Dimensions are in Inches [Millimeters]  
JP503S Mounting Footprint