



To ensure proper electrical and thermal performance there must be a grounding plane with 100% solder connection underneath the part



Dimensions are in Inches [Millimeters]
X190x-100 Rev A Mounting Footprint