



U.S. Department
of Transportation
Federal Aviation
Administration

Small Airplane Directorate
Atlanta Aircraft Certification Office
One Crown Center, Suite 450
1895 Phoenix Boulevard
Atlanta, GA 30349

FEB 12 2004

Ms. Mary Gayle Wright
Sr. Business Development Manager
Commercial Products
L-3 Communications, Display Systems
1355 Bluegrass Lakes Parkway
Alpharetta, GA 30004

Dear Ms. Wright:

This is in response to your February 1, 2004, request. Your request is for Federal Aviation Administration (FAA) authorization to identify the Pilot Vehicle Interface (PVI™) Series 600 Multi-function display (MFD), Terrain Awareness Warning (TAWS) Part Number listed below in accordance with the requirements of 14 CFR part 21, subpart O and the minimum performance standards of Technical Standard Orders (TSOs) C105 and C113, as well as RTCA document DO-160D:

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>OPERATING SOFTWARE PART NUMBER/VERSION</u>
V63A010-00-001-001	PVI MFD TAWS	OFP V63A016-01-000, Version 1.2 DCP V63A016-05-000, Version 1.1 ABP V63A016-02-000, Version 1.0

We find your Statement of Conformance dated February 1, 2004, and your Quality Control Systems Manual, Revision M, dated May 7, 2003, acceptable.

The following data as submitted by you will be retained on file for this authorization:

- a. L3 Environmental Qualification Form, Document Number V63A010-37-002, Revision -, dated January 30, 2004.
- b. L3 Software Configuration Index, Document Number V63A015-14-002, Revision -, dated December 23, 2003.

c. L3 Software Accomplishment Summary, Document Number V63A015-15-002, Revision -, dated January 30, 2004.

d. Plan for Software Aspects of Certification for the PVI™ 600 MFD, Document Number V63A015-10-002, Rev -, dated January 13, 2004.


This office accepts your statement of compliance with RTCA DO-178B, Level B category requirements. This compliance finding should not be considered an installation approval and the installation may be subject to additional software review relating to the integration of this equipment into an airframe. Verification of compatibility with a particular aircraft installation is the responsibility of the installer and may require further FAA analysis, possible flight test and changes to a Flight Manual Supplement.

Effective this date, you are authorized to identify the aforementioned Pilot Vehicle Interface (PVI™) Series 600 Multi-function display (MFD), Part Number and Software Versions with the applicable series TSO markings required by 14 CFR, subpart 21.607(d). This authorization is not transferable to another person or location and is effective until surrendered, withdrawn, or otherwise terminated by the Administrator.

Your responsibilities as a holder of a TSO authorization are outlined in 14 CFR, subpart 21.3 and 14 CFR, part 21, subpart 0. Any design change made to the TSO item must be forwarded to this office as outlined in 14 CFR, part 21.611, with minor change submittal intervals not to exceed six months.

The Systems Engineer for your program is Myles Jalalian, telephone number (770) 703-6073. The Technical Information Specialist is Lorraine Bush, telephone number (770) 703-6044.

Sincerely,



Eugene L. Bollin

Associate Manager

Atlanta Aircraft Certification Office