

# PRODUCT DISCONTINUANCE BULLETIN



**Issue Date:** August 31, 2005

**PDB Number:** PDB\_4065C.Doc

## Product

Symmetricom, Model 4065C Primary Frequency & Time Standard



**4065C**

## Overview

Symmetricom is discontinuing the Model 4065C Primary Frequency & time Standard and all associated options. The 4065C has reached the end of its technology product lifecycle and is being discontinued. Symmetricom is replacing the 4065C with the 5071A Primary Frequency Standard. The 5071A provides all the functionality previously available in the 4065C while offering improved frequency accuracy and long-term stability.

The 4065C discontinuance does not affect replacement beam tubes for this product. Symmetricom will continue to provide this service in accordance with service and warranty policies that are currently in place.

## Product Obsolescence Timeline

| Milestone         | Date             |
|-------------------|------------------|
| Last Day to Order | January 31, 2006 |

## Affected Models and Replacement Product Summary

| Current Model | Current Part #s                                          | Replacement Model | Replacement Part #       |
|---------------|----------------------------------------------------------|-------------------|--------------------------|
| 4065C         | 08490-101<br>08490-102<br>Including all special versions | 5071A             | 5071A-C001<br>5071A-C002 |

## Support Policy

Repair services and maintenance contracts are expected to be until January 31, 2010. In the event of parts or component obsolescence, repairs will be made on a best efforts basis. All other service options (spares support, telephone technical support, on-site maintenance, training, etc.) are available from Symmetricom Global Services (SGS) on a contract or case-by-case basis. Interested customers should contact SGS to check a product's eligibility for services and any applicable terms.

### Contact Information

Symmetricom Global Services      1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide

Symmetricom Customer Service:      1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA  
1-408-428-7907 worldwide  
support@symmetricom.com  
www.symmetricom.com

Timing, Test & Measurement Division:      3750 Westwind Blvd.  
Santa Rosa, CA 95403  
Telephone: 707-528-1230  
Facsimile: 707-527-6640