

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: June 30, 2011

PDB Number: PDB_VME_AT_OCXO.pdf

Product

Symmetricom, OCXO option for AT and VME based Time and Frequency Cards

No photo available

Overview

Symmetricom is announcing the discontinuance of the OCXO option for AT and VME based Time and Frequency Cards. The OCXO is a single line item addition (part number 11736-1000) to the bc620AT, bc635VME and bc637VME products. This optional OCXO, part number 11736-1000 is being discontinued. In addition, the TTM635VME-OCXO also uses part number 11736-1000 and this entire configuration is being discontinued.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	No longer for sale
Extended Warranty Contracts (maximum expiration date)	Not applicable
Repair End Date (Out-of-warranty repairs will not be available for this product beyond this date)	Not applicable
Customer Support Contracts (non-repair services)	Not applicable

Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
bc11736-1000	BC11736-1000	No replacement	No replacement
TTM635VME-OCXO	TTM635VME-OCXO	TTM635VME (TCXO version)	TTM635VME

Contact Information

Symmetricom Global Services: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service: 1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Government Business Unit: 3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640