

PRODUCT DISCONTINUANCE BULLETIN



Issue Date: June 30, 2011

PDB Number: PDB_bc824VXI.pdf

Product

Symmetricom, VXIbus Rubidium Standard



bc824VXI Rubidium Frequency Standard

Discontinued: bc824VXI Rubidium Frequency Standard

Overview

Symmetricom is announcing the discontinuance of the bc824VXI Rubidium Frequency Standard. This product has reached the end of its product lifecycle.

Product Obsolescence Timeline

Milestone	Date
Last Day to Order	August 15, 2011 or while supplies last, whichever comes sooner. (Six (6) left as of June 30, 2011).
Standard Warranty not available on last time buy.	No standard warranty available.
Repair End Date (Out-of-warranty repairs will not be available for this product beyond this date)	July 1, 2011.
Customer Support Contracts (non-repair services)	Not applicable.

Affected Models and Replacement Product Summary

Current Models	Current Part #s	Replacement Models	Replacement Part #s
bc824VXI	BC824VXI	No replacement	No replacement

Contact Information

Symmetricom Global Services:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide

Symmetricom Customer Service:

1-888-367-7966 (1-888-FOR-SYMM) toll-free in the USA
1-408-428-7907 worldwide
support@symmetricom.com
www.symmetricom.com

Government Business Unit:

3750 Westwind Blvd.
Santa Rosa, CA 95403
Telephone: 707-528-1230
Facsimile: 707-527-6640